

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH9009A
 MAKE HYUNDAI
 MODEL IONIQ

DATE: 02.12.22
 MVA JUMANI
 DOA: 01.12.22

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	BOOTLID COVER			\$2,549.70
1	REAR BUMPER ASSY			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER BEAM			\$394.80
10	REAR BUMPER CLIPS			\$22.00
1	FOG LAMP			\$201.50
1	ANTENNA ASSY – SMARTKEY			\$40.50
1	BOOTLID EMBLEM – IONIQ			\$31.30
1	BOOTLID EMBLEM – HYBRID			\$24.30
1	BOOTLID EMBLEM – H			\$28.00
1	REAR BUMPER LOWER CENTRE MOLDG			\$155.00
1	REAR BUMPER STAY - LH			\$138.10
1	REAR BUMPDER STAY - RH			\$138.10
1	REAR BUMPER TOW COVER			\$98.80
	SUB TOTAL		3865.75	\$4,732.75
	LESS 20%		773.15	\$946.55
	DISCOUNTED TOTAL		3092.60	\$3,786.20
	REAR NUMBER PLATE			\$50.00
	REVERSE SENSOR			\$180.00
	REAR BOOTLID COMFORT LOGO			\$30.00
	REAR BOOTLID TEL.NOS LOGO			\$30.00
	REAR BOOTLID APPS LOGO			\$40.00
	REAR BUMPER MAT			\$50.00
	WINDSCREEN SEALANT			\$46.00
				\$426.00
	Labour Charge			
	PANEL BEATING			\$1,200.00
	SPRAY PAINT			\$600.00
	REMOVE / REFIX REVERSE SENSOR			\$50.00
	CHECK WIRING			\$50.00
	REMOVE / REFIX REAR WINDSCREEN GLASS			\$120.00
			4828.60	
			965.72	
	TOTAL LABOUR		= 3862.88	\$2,020.00
	ESTIMATE TOTAL		2385.98	\$6,232.20

Dent
 cut
 ? cut
 ? XNN
 NCC
 crn
 ? XNN
 NCC
 NCC
 NCC
 ? XNN
 ? XNN
 ? XNN
 SCR

NET crn
 NET crn
 NET NCC
 NET NCC
 NET NCC
 NET NCC
 NET NCC
 NET NCC
 700
 500
 30
 X NN
 80

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

1 rfm 2/12/22
 L/S 4 days

1310