



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|--|-----------------|---|--|
| STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705 | | | Ref: CS/SMR22012601/Rvy3m4 Date: 03/04/2023 Code: SMR | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SHF 309J | Veh. Inspected | SMW 6419L | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | TAX/12/22/2038 | Excess (\$) | 0.00 | |
| Assign From | ANA MAGNAYE | Assign Date | 16/12/2022 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HYUNDAI AE IONIQ 1.6 DCT | c.c | 1580 | |
| Engine No. | HIDDEN | Year of Reg. | 2020 | |
| Chassis No. | KMHC851CVLU201156 | Colour | GREY | |
| Odometer | 148821 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | FAIR | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 195/65R15 | WEST LAKE | 6 mm | |
| L/H Front Tyre | 195/65R15 | WEST LAKE | 6 mm | |
| R/H Rear Tyre | 195/65R15 | WEST LAKE | 6 mm | |
| L/H Rear Tyre | 195/65R15 | WEST LAKE | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 15/12/2022 | Inspection Date | 16/12/2022 | |
| Survey held at | PEGASUS ENGINEERING & TRADING PTE LTD 74 Kian Teck Road Singapore 628800 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 6 Working Days | |