

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO SHB4932D
 MAKE HYUNDAI
 MODEL IONIQ

DATE: 15.12.22

MVA JUMANI

DOA: 14.12.22

INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	REAR DOOR ASSY RH			\$2,147.90	/DD
1	REAR ROCKER PANEL RH			\$290.00	/BUL
1	REAR FENDER WHEEL HOUSING RH	SVC	X	\$1,406.20	?
1	REAR FENDER SHIELD RH	TN	/	\$173.60	?
1	REAR BUMPER CENTRE MOULDING			\$451.25	/CRA
1	REAR BUMPER ASSY			\$459.40	/CRA
1	REAR BUMPER SIDE BRACKET RH	SVC	X	\$55.80	?
1	REAR BUMPER AIR DUCT			\$87.30	/BUL
1	ASSY BSD BLIND SPORT RADER	DEF	/	\$1,784.40	1500 X SVC
10	REAR BUMPER CLIPS			22.00 \$2.20	/NEC
1	REAR REFLECTOR RH	SVC	X	\$41.45	?
1	REAR BUMPER UNDER OCVER			\$225.00	/CRA
1	REAR FENDER RH			\$1,768.30	/DD
1	WHEEL RIM	LUT	/	\$1,124.20	18 X R
1	WHEEL RIM CAP			\$346.40	/SCR
1	REAR WHEEL BRG ING & HUB	DEF	/	\$544.00	?
1	REAR TRAILING ARM RH	DEF	/	\$265.40	?
1	REAR ASSIST RH	BT	/	\$227.90	?
1	REAR S/ABSORBER RH	BT	/	\$230.50	?
1	RERA S/ABSORBER MOUNTIBG RH	SVC	X	\$133.10	?
1	REAR UPPER ARM RH	DD	/	\$239.50	?
1	REAR LOWER ARM RH	SVC	X	\$393.10	?
1	REAR KNUCKLE ARM RH	DEF	/	\$538.10	?
1	TAILLAMP ASSY RH			\$870.40	/SCR
SUB TOTAL				11,795.55	\$13,454.70
LESS 20%					\$2,690.94
DISCOUNTED TOTAL				9,104.61	\$6,422.04
					\$10,763.76
					NET
REAR DOOR APPS LOGO					\$80.00
TYRE RH				Y 60%	SCR 129.60 \$216.00
RERA BUMPER AMT					\$50.00
					NET / NEC
					\$346.00
Labour Charge					
PANEL BEATING					\$1,400.00
SPRAY PAINT					\$1,000.00

NET
 NET / NEC
 NET
 NET / NEC

1,200
 900

REMOVE / REFIX DOOR PARTS			\$120.00	50
CHECK WIRING			\$50.00	30
TUFF KOTE			\$60.00	50
REMOVE/REFIX REAR UPHOLSTERY			\$150.00	50
REMOVE/REFIX REAR SUSPENSION			\$200.00	? 150
ADJUST FOUR WHEEL ALIGNMENT		NN	x \$120.00	? 100
TOWING FEE-KING DOLLY			\$150.00	NNN
		12,226.04	\$3,250.00	
		12,126.04	\$2,430.00	
			\$14,359.76	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NA2 LKK

15/12/2022 1615

LIS

4 DAYS

CHECK ITEM PHOTOS

AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TYPE OF INS. : INCOME

SURVEY BY : LKK-NAZ

DATE : _____