

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

VEHICLE NO SHA4121H

MAKE/REG HYUNDAI /

MODEL I-40

DATE 15.12.2022

MVA CHIANG/ INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT DOOR RH			\$670.00
1	FRONT FENDER SHIELD RH			\$174.90
1	FRONT FENDER RH			\$663.00
1	FRONT WHEEL COVER RH			\$217.20
	<b>SUB TOTAL</b>			<b>\$1,725.10</b>
	<b>20.00%</b>			<b>\$345.02</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$1,380.08</b>
1	FRONT DOOR ADVERTISEMENT			\$100.00
1	FRONT FENDER ADVERTISEMENT			\$100.00
1	FRONT DOOR COMFORT STICKER			\$75.00
				<b>\$275.00</b>
	<b>Labour Charge</b>			
	Panel Beating			<del>\$450.00</del>
	Spray Painting ( Frt pillar & frt door)			<del>\$600.00</del>
	Remove/Refix door parts			\$60.00
	<b>TOTAL LABOUR</b>			<b>\$1,110.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$2,765.08</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will				
be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

NAZ LKK  
16/12/2022 1618  
LIS  
3 Days  
CHECK ITEM PHOTOS  
AFTER REPAIR PHOTOS

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: