

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47
 AUTOBAY SINGAPORE 417883
 Tel : 6509 5521 / 65095524 Fax : 6509 5523
 Email: Sales@Leebrothers.com.sg

*TP Chin
Xiao Tang*

Vehicle Number: GBE7422U

Vehicle Model: NISSAN NV200

PARTICULAR		AMOUNT
QTY	LIST PRICE	SS
1	TAILGATE -LH <i>Dented</i>	\$ 1,560.90 ✓ 1469
1	TAILGATE LOGO <i>new</i>	\$ 79.90 ✓
1	TAILGATE EMBLEM ' NV 200' <i>new</i>	\$ 124.20 ✓
1	TAILGATE OUTER GARNISH <i>crushed</i>	\$ 351.50 ✓
1	TAILGATE WIPE MOTOR <i>Dmg</i>	\$ 481.90 ✓
1	TAILGATE LOCK - LOWER <i>Dmg</i>	\$ 186.10 ✓
1	TAILGATE LOCK STRIKER <i>new</i>	\$ 110.50 ✗
1	TAILGATE LOCK - CTR <i>Dmg</i>	\$ 289.30 ✓
1	TAILGATE LOCK ACTUATOR <i>new</i>	\$ 441.50 ✗
1	TAILGATE LOCK - TOP <i>new</i>	\$ 186.10 ✗
1	TAILGATE OPENING W/STRIP <i>lit</i>	\$ 261.90 ✓
1	TAILGATE CHECKER <i>new</i>	\$ 138.10 ✗
2	TAILGATE HINGES @\$121.50 <i>new</i>	\$ 243.00 ✗
1	TAILGATE INNER TRIM <i>new</i>	\$ 186.90 ✗
10	TAILGATE INNER TRIM CLIPS @\$5.50 <i>new</i>	\$ 55.00 ✗
1	TAILGATE - RH <i>Dented</i>	\$ 1,253.70 ✓ 1102
1	TAILGATE SEAL <i>new</i>	\$ 126.20 ✗
2	TAILLAMPS - R/L @\$283.20 <i>crushed</i>	\$ 566.40 ✓
2	TAILLAMP FILLER PANELS - R/L \$481.60 <i>new</i>	\$ 963.20 ✗
1	REAR BUMPER <i>Dented</i>	\$ 632.70 ✓
2	REAR BUMPER REFLECTOR @\$61.50 <i>new</i>	\$ 123.00 ✗
1	REAR BUMPER INNER FOAM <i>crushed</i>	\$ 194.70 ✓
2	REAR BUMPER SIDE RETAINERS - R/L @\$48.90 <i>Dmg</i>	\$ 97.80 ✓
1	REAR END PANEL <i>Dented</i>	\$ 481.50 ✓
1	REAR END PANEL INNER MEMBER <i>Reps</i>	\$ 899.60 ✗
1	REAR END PANEL TOP GARNISH <i>Dented</i>	\$ 138.10 ✓
10	REAR END PANEL TOP GARNISH CLIPS @\$5.50 <i>new</i>	\$ 55.00 20.
		\$ 10,228.70
		LESS 10% \$ 1,022.87
		<u>\$ 9,205.83</u>

*6477
5829.30*

LEE BROTHERS AUTOMOTIVE PTE. LTD.

Vehicle Number: GBE7422U

Vehicle Model: NISSAN NV200

SPECIAL NETT ITEMS

2	(SET) TAILGATE GLASS SEALANT - R/L	<i>3 per</i>	\$	120.00	<i>80</i>
2	(SET) TAILGATE GLASS FOAM TAPE - R/L		\$	120.00	<i>80</i>
1	REAR STICKER "70KM/H"	<i>3 per</i>	\$	10.00	<i>✓</i>
1	REAR STICKER "6 PAX"	<i>3 per</i>	\$	10.00	<i>✓</i>
1	(SET) REAR BUMPER CLIP	<i>Mer</i>	\$	45.00	<i>30</i>
1	(SET) REAR REVERSE SENSOR	<i>2 per</i>	\$	280.00	<i>20</i>
			\$	<u>585.00</u>	

410

LABOUR CHARGES

TO CHECK REAR ELECTRICAL WIRING	\$	80.00	<i>30</i>
TO REMOVE & REPLACE TAILGATE GLASS - R/L	\$	300.00	<i>120</i>
TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	\$	120.00	<i>60</i>
TO REMOVE & REPLACE EXHAUST SYSTEM	\$	100.00	<i>+</i>
TO REMOVE AND REPLACE REVERSE CAMERA & SENSORS	\$	80.00	<i>✓</i>
TO TUFF KOTE	\$	180.00	<i>60</i>
TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	\$	1,500.00	<i>80</i>
TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	\$	1,500.00	<i>80</i>
	\$	<u>3,860.00</u>	

1970

ESTIMATE PARTS AND LABOUR GRAND TOTAL :

\$ 13,650.83

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

PAGE 2

total: 8209.30

L/S: 6.5K

06 Days