



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22012631/Any3m4 Date: 05/01/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 5763M	Veh. Inspected	SLN 761X	
Policy No.		Coverage (\$)	0.00	
Claim No.	BVS22/1442	Excess (\$)	0.00	
Assign From	TED SEAH	Assign Date	16/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM	c.c	1799	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	RN61084884	Colour	BRONZE	
Odometer	153620 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	AUFINE	6 mm	
L/H Front Tyre	195/65 R15	AUFINE	6 mm	
R/H Rear Tyre	195/65 R15	AUFINE	6 mm	
L/H Rear Tyre	195/65 R15	AUFINE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/12/2022	Inspection Date	19/12/2022	
Survey held at	JDM AUTOCARE 1 KAKI BUKIT AVENUE 6, #01-51, AUTOBAY @ KAKI BUKIT, SINGAPORE 417883			
5a. Remarks				
A)REGISTRATION DATE: 15 DEC 2008 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	