



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: LOH CYNTHIA		Ref: CS/ASM22012645/Aqp3e2 Date: 27/03/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 9120K	Veh. Inspected	SMH 5565H
Policy No.		Coverage (\$)	0.00
Claim No.	S2M04GN9	Excess (\$)	0.00
Assign From	LOH CYNTHIA	Assign Date	19/12/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA FREED	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GB71085320	Colour	RED
Odometer	73131 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65 R15	KAPSEN	6 mm
L/H Front Tyre	185/65 R15	KAPSEN	6 mm
R/H Rear Tyre	185/65 R15	KAPSEN	6 mm
L/H Rear Tyre	185/65 R15	KAPSEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/12/2022	Inspection Date	19/12/2022
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	