

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

TP Budget Direct.
vecon

SJ AUTO PTE LTD
 60 JALAN LAM HUAT #05-11 CARROS
 CENTRE
 SINGAPORE 737869

TAX INVOICE

Repair Code : CLM17530

Date in : 19/12/2022

Vehicle Num. : SNG8349P

Model : MAZDA3 4DR 1.5 AT M-HYBRID CLASSIC I2

Chassis/Eng# : JM6BP2SAAN1151305/P520828855

Contact : 97711118, 98337705

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Rehind</i>	1	876.00	876.00 ✓ 876.00
FRONT BUMPER LH CHROME MOULDING <i>cracked</i>	1	298.00	298.00 ✓ 298.00
FRONT BUMPER SIDE RETAINER L/R <i>LH 2nd</i>	1	77.00	77.00 77.00
FRONT LH CONTROL UNIT <i>new</i>	1	3948.10	3948.10 X 3,948.10
FRONT LH FENDER <i>Repair</i>	1	425.00	425.00 X 425.00
FRONT LH FENDER INNER SHIELD <i>new</i>	1	185.00	185.00 X 185.00
FRONT LH HEADLAMP <i>wt</i>	1	3749.00	3749.00 ✓ 3,749.00
FRONT LH HEADLAMP LOWER BRACKET <i>cracked</i>	1	68.00	68.00 ✓ 68.00
FRONT NOSE PANEL <i>torn</i>	1	579.00	579.00 ✓ 579.00
FRONT NOSE PANEL CLIPS <i>new</i>	8	3.50	28.00 20.00
FRONT NOSE PANEL LH BRACKET <i>new</i>	1	58.00	58.00 X 58.00
FRONT NOSE PANEL RIVET <i>new</i>	10	5.90	59.00 20.00
FRONT NOSE PANEL RUBBER SEAL <i>new</i>	1	38.00	38.00 X 38.00
Subtotal before discount			10,465.10
Percentage discount 20%			2,093.02
Sub-total 1			8,372.08
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	50.00 30.00
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	50.00 X 50.00

5687
4549.60

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SJ AUTO PTE LTD
 60 JALAN LAM HUAT #05-11 CARROS
 CENTRE
 SINGAPORE 737869

Contact : 97711118, 98337705

TAX INVOICE

Repair Code : CLM17530
 Date in : 19/12/2022
 Vehicle Num. : SNG8349P
 Model : MAZDA3 4DR 1.5 AT M-HYBRID CLASSIC I2
 Chassis/Eng# : JM6BP2SAAN1151305/P520828855

Subtotal before discount		100.00
Percentage discount 0%		0.00
Sub-total 2	30	100.00
Parts-total		<u>8,472.08</u>

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	30	80.00
To reset system after repair works	125 X	250.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	400	500 600.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	200	500.00
To apply anti-rust chemical on repaired and replaced panel.	30	50.00
Labour Total		<u>1,480.00</u>
Parts & Labour Total		<u>9,952.08</u>

760.

*** This is a computer-generated document which requires no signature.***

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Adrian Lij
 4/5 19/12/22
 04 Days

total: 5339.60
 h/s: A.2K.