



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HL ASSURANCE PTE LTD 11 KEPPEL ROAD #11-01 ABI PLAZASINGAPORE 089057			Ref: CS/HLA22012682/Aqy3	
			Date: 20/12/2022	
			Code: HLA	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMT 1876Z	Veh. Inspected	SMW 2855L	
Policy No.	MP319962	Coverage (\$)	0.00	
Claim No.	MPC03918/SG	Excess (\$)	0.00	
Assign From	GOH SIEW GEOK	Assign Date	20/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	16/12/2022	Inspection Date	20/12/2022	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				