



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22012686/Rny3e2 Date: 04/07/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMB 1596B	Veh. Inspected	SLG 4281A
	Policy No.		Coverage (\$)	0.00
	Claim No.	BUS/12/22/5027	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	20/12/2022
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3 SEDAN 1.5L SP	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	JM6BM42A8G0346570	Colour	BLUE
	Odometer	449996 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	RYDANZ	6 mm
	L/H Front Tyre	205/60 R16	RYDANZ	6 mm
	R/H Rear Tyre	205/60 R16	RYDANZ	6 mm
	L/H Rear Tyre	205/60 R16	RYDANZ	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	18/12/2022	Inspection Date	20/12/2022
	Survey held at	No. 4 Jalan Besut S(619557)		
	Repairer	LION CITY RENTALS PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	