




LION CITY RENTALS PTE LTD
4 Jalan Besut S(619557)

SMRT

Date : 19-Dec-22

Attn : MOTOR CLAIMS DEPT

VEHICLE NO. : SLG4281A
 CHASSIS NO : JM6BM42A8G0346570
 MAKE / MODEL : Mazda 3
 DATE OF
 ACCIDENT: 18-Dec-22
 YOUR INSURED VEHICLE NUMBER : SMB1596B



<u>PARTS DISCRIPTION</u>		<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	FRONT BUMPER <i>de</i>	1PC	\$1,020.00	\$1,020.00
2	FRONT BUMPER RETAINER <i>sea</i>	1PC	\$89.00	\$89.00 38.70
3	FRONT HEADLAMP <i>? X</i>	1PC	\$825.00	\$825.00 X
4	FRONT FENDER <i>bt</i>	1PC	\$495.00	\$495.00 393
5	FRONT FOGLAMP <i>X</i>	1PC	\$130.50	\$130.50 X
6	FRONT FOGLAMP COVER <i>X</i>	1PC	\$48.60	\$48.60 X
7	FRONT FENDER UNDER-DUSCT COVER <i>cm</i> (shield)	1PC	\$139.50	\$139.50 ✓
8	FRONT GRILLE ASSY <i>cm</i>	1PC	\$304.50	\$304.50 ✓
9	FRONT BUMPER UNDER-DUST COVER <i>cm</i>	1PC	\$145.00	\$145.00 ✓
10	FRONT GRILLE INNER BRACKET <i>? X</i>	1PC	\$420.00	\$420.00 X
			Total	\$3,617.10
			Less 20%	\$723.42
			Total	\$2,893.68

<u>SPECIAL NETTS</u>		<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	FRONT BUMPER CLIPS <i>cm</i>	1	\$ 40.00	\$ 40.00 430
2	FRONT FENDER UNDER-DUSCT COVER CLIPS <i>cm</i>	1	\$ 40.00	\$ 40.00 30 60
			Total	\$ 80.00

<u>LABOUR CHARGES</u>			
1	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT, CUT / WELD, STRAIGHTEN CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS.	\$	1,000.00 500
2	PUTTY AND SPRAY PAINT ALL AFFECTED AREAS (INNER/OUTER)	\$	800.00 400
3	TO REMOVE, REARRANGE ELECTRICAL WIRING, CHECK LIGHTING & RESET HEADLAMP FOCUSING	\$	180.00 30 30
4	COMPUTERIZED ALIGNMENT	\$	120.00 60

TOTA	\$	2,100.00
TOTAL PARTS	\$	2,973.68
GRAND TOTAL	\$	5,073.68

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resue
Hp 90010068

4 days

HS

20/2/22 @1440

Resue after repair

1632.56

60.00

990.00

2682.56

20%

2146.04

HS - \$2,150 / 4 days