





HSIAO Tony

VEHICLE NO: FBR 7125J

| QTY  | DESCRIPTION                              | CONDITION | REPAIRER'S<br>ESTIMATE(\$\$) | SURVEYOR'S<br>ADJUSTMENT |
|------|------------------------------------------|-----------|------------------------------|--------------------------|
|      | <b>PARTS (NETT ITEMS)</b>                |           |                              |                          |
| 1    | Front Headlamp cover complete            | REFIX     | 0.00                         | See X                    |
| 1    | Front wheel fender                       |           | 90.00                        | cut ✓                    |
| 1    | RHS front fairing                        |           | 180.00                       | cut ✓                    |
| 1    | LHS front fairing                        |           | 180.00                       | cut ✓                    |
| 1    | RHS & LHS Signal lamp                    | REFIX     | 0.00                         | See X                    |
| 1    | RHS Board Foot rest side protector       |           | 98.00                        | cut ✓                    |
| 1    | RHS Rear seat fairing                    |           | 150.00                       | cut ✓                    |
| 1    | Handle bar                               |           | 350.00                       | See X                    |
| 1set | Handle bar grips RH & LH                 |           | 48.00                        | 11 X                     |
| 1set | Handle bar balancer RH & LH              |           | 38 75.00                     | 0/5 cut 1/2 C            |
| 1    | Brake lever                              |           | 75 90.00                     | cut ✓                    |
| 1    | Clutch lever                             |           | 75 90.00                     | cut ✓                    |
| 1    | LHS side mirror                          |           | 50.00                        | 320 ✓                    |
| 2    | Front signal lamps RH & LH @ 110         | REFIX     | 0.00                         | See X                    |
| 2    | Front signal lamp cover complete (black) |           | 175.00                       | ground ✓                 |
| 1    | Front fairing                            |           | 485 700.00                   | cut ✓                    |
| 1    | Side stand                               |           | 75.00                        | cut ✓                    |
| 1    | Main stand                               |           | 120.00                       | cut ✓                    |
| 1    | Exhaust silencer                         |           | 250.00                       | 20/20 ✓                  |
| 1    | Exhaust silencer protector               |           | 78.00                        | 715 ✓                    |
|      |                                          |           | 2799.00                      |                          |
|      |                                          | less 10%  | 279.90                       | 10%                      |
|      |                                          |           | 2519.10                      |                          |
|      | <b>SPECIAL NETT ITEMS</b>                |           |                              |                          |
| 1    | IU Unit with holder                      |           | 150.00                       | 11 X                     |
| 1set | Bolts / Misc / seals                     |           | 30.00                        | 11 X                     |
| 1    | Rear box                                 |           | 250.00                       | cut ✓                    |
| 1    | Rear box support bracket                 |           | 90.00                        | cut ✓                    |
|      | <b>TOTAL PARTS</b>                       |           | 3039.10                      |                          |

not Allowed  
du  
1/5 #2000  
4 days  
20/11/22

VEHICLE NO: FBR 7125J

| S/N | DESCRIPTION                                              | REPAIRER'S<br>ESTIMATE (\$\$) | SURVEYOR'S<br>ADJUSTMENT |
|-----|----------------------------------------------------------|-------------------------------|--------------------------|
|     | <b><u>LABOUR</u></b>                                     |                               |                          |
| 1   | To remove and replace damaged parts and components       | 450.00                        | 300                      |
| 2   | To remove, refix wiring system at accident damaged areas | 60.00                         | mx                       |
| 3   | To spray paint RHS front fairing and RHS rear fairing    | 150.00                        | mx                       |
| 4   | To align front fork                                      | 60.00                         | mx                       |
| 5   | Transport motorcycle to workshop for repairs             | 60.00                         | mx                       |
|     | Labour Total :                                           | 780.00                        |                          |
|     | TOTAL (PARTS & LABOUR):                                  | 3819.00                       |                          |

**NOTE:** The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

P-2119  
102  
1907.1  
340