

JM66L1072K0311764

TP Somp
Veron

JDM AUTOCARE

BLK 1 KAKI BUKIT AVENUE 6, #01-51, AutoBay@Kaki Bukit Singapore 417883
UEN NO : 53060650W

DATE : 19/12/2022

VEHICLE NO : SLE319M MAZDA 6 2.0

ITEMS	QTY	Amount
1 REAR BOOTLID <i>Py5</i>	1	\$1,158.60 <i>x</i>
2 REAR BOOTLID LOCK <i>new</i>	1	\$280.40 <i>+</i>
3 REAR BOOTLID LOGO <i>new</i>	1	\$108.90 <i>-</i>
4 REAR BOOTLID EMBLEM MAZDA 6 <i>new</i>	1	\$94.70 <i>-</i>
5 REAR BOOTLID EMBLEM SKYACTIV <i>new</i>	1	\$87.50 <i>-</i>
6 REAR BUMPER <i>Delid</i>	1	\$1,285.60 <i>-</i>
7 REAR BUMPER SIDE RETAINER @\$72.30 <i>new</i>	2	\$144.60 <i>-</i>
8 REAR BUMPER REINFORCEMENT <i>Delid</i>	1	\$745.10 <i>583</i>
9 REAR BUMPER TOW COVER @\$58.30 <i>new</i>	2	\$116.60 <i>58.30</i>
10 REAR BUMPER REFLECTOR @\$154.30 <i>new</i>	2	\$308.60 <i>+</i>
11 REAR BUMPER CENTER BRACKET <i>new</i>	1	\$48.10 <i>-</i>
12 REAR WEATHER STRIPE <i>new</i>	1	\$172.80 <i>x</i>
13 REAR END PANEL <i>new</i>	1	\$676.30 <i>x</i>
14 REAR END PANEL TOP GARNISH <i>new</i>	1	\$180.10 <i>+</i>
15 REAR EXHUAUST MUFFLER <i>new</i>	1	\$1,899.60 <i>+</i>
		<u>\$7,307.50</u>
DISCOUNT 20%		<u>\$1,461.50</u>
TOTAL		<u>\$5,846.00</u>

2410.70

1928.56

SLE319M MAZDA 6 2.0

SPECIAL NETT ITEM

- 1 REAR BUMPER CLIPS *me*
- 2 REAR BUMPER LOWER SPOILER *Del d*
- 3 REAR BUMPER LOWER SPOILER LAMP *me me*
- 4 REAR BUMPER LOWER SPOILER SEAL *me*
- 5 REAR END PANEL SEALANT *me n*

QTY	Amount
1	\$80.00 30
1	\$850.00 600
1	\$280.00 x
1	\$160.00 50
1	\$120.00 x

\$1,490.00

\$7,336.00

Labour charges

- 1 TO REMOVE , REINSTALL ALL ELECTRICAL WIRING , LIGHTING
- 2 TO SUPPLY LABOUR , WORKMANSHIP TO REMOVE AND REINSTALL AFFECTED AREA
- 3 TO SPRAY PAINT AND RESPRAY ACCIDENT AFFECTED AREAS
- 4 TO APPLY TUFF COAT

\$80.00 30
\$1,000.00 400
\$900.00 400
\$300.00 40

\$2,280.00

\$9,616.00

Adrian Lj
h/s 21/12/22.
03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 3478.56

h/s: 2.7K