



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Ref: CS3/ASM22012699/Kvp3

Date: 20/12/2022

Code: ASM

**1. Policy Particulars :- (THIRD PARTY CLAIM)**

<b>Insured Veh.</b>	SH 8592M	<b>Veh. Inspected</b>	GBH 1090S
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S2M04GP7	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ANG YVONNE	<b>Assign Date</b>	19/12/2022

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>		<b>c.c</b>	0
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	
<b>Chassis No.</b>		<b>Colour</b>	
<b>Odometer</b>	-	<b>Steering</b>	
<b>Brakes</b>		<b>Modification</b>	
<b>General</b>			

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm

**4. Description of Damages**

--	--

**5. General Information**

<b>Accident Date</b>	17/12/2022	<b>Inspection Date</b>	19/12/2022
<b>Survey held at</b>	MJE MOTOR BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642		

**5a. Remarks**

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--