

(08/11/11) Web

ASS. REC. BY: [Signature]

REF:

CS/CTI 220 12706/Rvp3

959H

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To Inspect Vehicle No: SKQ 899D

at Workshop n/s PERFORMANCE

of 303, MELKORRA RD

Insured: CTI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 750

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
-----	-----

Bal. or Market Value: 226K

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKQ 899D Yr Regn: 2021 / April

Type: ☒ Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐ Truck / ☐ Trailer or

Make: B.M.W 520I LUX ADAP HL c.c. 1998

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 272 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA72A9050W07884

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt

Steering: In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: NI / ☒ STD / ☐ RIM or

Tyre Size: F: 245/40R19 R: _____

BS / ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☒ PIR / ☐ SUMI / ☐ TOYO / ☐ YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. <u>22/10/22</u>	D.O.I. <u>22/12/22</u>

Survey held at PERFORMANCE

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 125K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

) S + RS, SI

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

TOTAL

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 64376
Date Estimated : 15/12/2022
Prepared By : Han Kwan Yong

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Hartono Halim
1001 Bukit Timah Road
#05-05

Singapore 596289

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKQ899D	WBA72AG050WX07884	30/08/2021	520i Sedan	7730

DESCRIPTION

To replace rear bumper

To respray rear bumper

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

To check electrical wiring system and lighting at the rear section for proper function.

Sundries.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VALUE

850 1,275.00

986 1,038.00

168 177.00

168 177.00

80.00

Total Labour 1: 2,747.00

DESCRIPTION

REAR LH GUIDE

REAR BUMPER TRIM PANEL (PDC/ repair

REAR LH REAR REFLECTOR

DESCRIPTION	QTY	PRIC	VALUE
# REAR LH GUIDE	1	179.90	179.90
# REAR BUMPER TRIM PANEL (PDC/ repair	1	1,664.50	1,664.50
REAR LH REAR REFLECTOR	1	41.75	41.75

Total Parts : 1,886.15

Claims On / 3rd Party / Uninsured Losses / Direct Settlement

Regn No

Date&Time

22/12/22 @ 16:25

In No

Loss \$

750

Surveyor's Name

Surveyor's Tel

RASHUL
96010068

Used Yes No

Auth Insured

REGN

Surveyor

No. of Working days to attend

3 days

Labour 1	:	2,747.00
Parts	:	1,886.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	324.32
Grand Total	:	4,957.47



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 959H

Vehicle Details

Vehicle No.: SKQ899D
Vehicle to be Exported: No
Intended Deregistration Date: 22 Dec 2022
Vehicle Make: B.M.W.
Vehicle Model: 520I LUXURY ADAP LED HL
Primary Colour: White
Manufacturing Year: 2020
Engine No.: 23226273B48B20A
Chassis No.: WBA72AG050WX07884
Maximum Power Output: 137.2 kW (183 bhp)
Open Market Value: \$54,183.00
Original Registration Date: 30 Aug 2021
First Registration Date: 30 Aug 2021
Transfer Count: 1
Actual ARF Paid: \$69,530.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Aug 2031
PARF Rebate Amount: \$52,147.00

Intended COE Rebate Details

COE Expiry Date: 29 Aug 2031
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$56,001.00
COE Rebate Amount: \$48,639.00
Total Rebate Amount: \$100,786.00

The information contained herein is correct as at 22 Dec 2022

BMW 5 Series 520i Luxury

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

BAVARIAN
MARQUES

Price	\$215,000		
Depreciation ⓘ	\$22,160 /yr View models with similar depre	Reg Date	08-Feb-2021 (8yrs 1mth 16days COE left)
Mileage	45,000 km (24.1k /yr)	Manufactured ⓘ	2020
Road Tax ⓘ	\$1,210 /yr	Transmission	Auto
Dereg Value ⓘ	\$90,208 as of today (change)	Fuel Type	Petrol-Electric
COE ⓘ	\$46,790	OMV ⓘ	\$54,183
Engine Cap	1,998 cc	ARF ⓘ	\$69,530
Curb Weight ⓘ	1,610 kg	Power	137.2 kW (183 bhp)