

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305539957

Date 22.12.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No. SH8725Y

Date of Accident : 13.12.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill 703A **INCOME** — **GV 9090G**
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges
 - Total for Part-By-Part Repair Cost**
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% , **\$1,200.00**
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : 

Name : NAZ

Date : 9/1/2023

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305539957
 REGN NO : SH 8725Y
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4A)
 DATE OF REGN : 19.12.2019
 DATE/TIME IN : 19.12.2022 10:30
 ACCIDENT DATE : 13.12.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2282-G	XX COVER REAR BUMPER	1	503.04	25.00	377.28	/CRA
0002	04-01-0302-2267-G	BUMPER CLIPS	10	22.00	25.00	16.50	-NEC
0003	04-01-0302-2287-G	GUARD-REAR BUMPER CENTER	1	654.96	25.00	491.22	/CRA
0004	04-01-0302-2288-G	REINFORCEMENT -ASSY REAR	1	378.32	25.00	283.74	?X SVC

SUB-TOTAL : 1,168.74

JOB NATURE

0000	PB	PANEL BEATING		400.00		350
0001	SP	SPRAYPAINT CHARGE		300.00		250
0002	L	REMOVE/REFRAX REVERSER SENSOR		50.00		30

SUB-TOTAL : 750.00

TOTAL : 1,918.74

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

NA2 LKX
 19/12/2022 1751
 . LIS
 2 Days
 CHECK ITEM PHOTOS
 AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: