

REPAIR ESTIMATE

Date: 19/12/2022

Insurance: INCOME

MVA: MS. LOKE Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$ 553.00
1	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER LOWER COVER			\$ 228.00
	SUB TOTAL			\$ 803.00
	LESS 20%			\$ 160.60
	DISCOUNTED TOTAL			\$ 642.40
	REAR BUMPER RUBBER MAT			\$ 50.00
				\$ 50.00
	Labour Charge			
	PANEL BEATING			\$ 300.00
	SPRAY PAINTING CHARGE			\$ 300.00
	REMOVE/REFIX REVERSE SENSOR			\$ 60.00
	TOTAL LABOUR			\$ 660.00
	ESTIMATE TOTAL			\$ 1,352.40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NA 2 LYK

19/12/2022 1620

L/S

2 DAYS

AFTER regular photos