



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

22/12/2022

Survey Details:

Date of loss	27-Nov-22
Date of appointment	21-Dec-22
Date of survey	21-Dec-22
Location of survey	FUTURE SCOOTERING

Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	FBL 2891U
Make and Model	SUZUKI UH200AL6 BURGMAN
Date of registration	17/8/2016
Excess	-
Market Value	\$ 8,000.00
Parf Rebate	\$ 2,196.00
Nett Loss	\$ 5,804.00

Repair details:

Initial Estimate	\$ -
------------------	------

Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
Total	\$ -
Lump Sum(if applicable)	

Number of days for repair	4
----------------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

The estimate repair cost of the damaged vehicle is in the region of \$4,000.00 - \$5,000.00.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	