



Your Ref : 2543683405SG

Date: 18th Jan 2023

Our Ref : CC3/AIG22012767/Rqy3e2

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #09-16

AIG Building

Singapore 079120

(The Motor Claims Department)

Dear Sir/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SLF 8283Z
ACCIDENT ON 29/06/2022**

Instruction was received to inspect the vehicle Reg. No. SLF 8283Z. The inspection was conducted on 29/11/2022 at the premises of M/s Premium Automobiles Pte Ltd (Ubi), 55 Ubi Road 1, Singapore 408699.

The following information was recorded: -

Registration Number	: SLF 8283Z
Make & Model	: Audi RS E-Tron GT
Year of Registration	: 2021
Body Colour	: Black
Chassis Number	: WAUZZZFW7N7902024

The vehicle sustained damages at the n/s front portion and o/s body. The estimate repair cost of such vehicle is \$642,947.00 (Sin Dollars: Six Hundred Forty-Two Thousand Nine Hundred and Forty-Seven only) (Details see photographs enclosed).

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 517,000.00

Less: LTA Reimbursement Value (RV)

(S\$ 172,428.00)

S\$ 344,572.00

Less: Excess

(S\$ 2,000.00)

Nett Liability

S\$ 342,572.00

(b) If the vehicle to be "Repair"

Repair Cost

S\$ 642,947.00

Less: Excess

(S\$ 2,000.00)

Nett Liability

S\$ 640,947.00


(a) – (b) =

(S\$ 298,375.00)

=====

The amount of estimated saving of S\$298,375.00 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser



K.K.LAU

MSc(Eng M), B Eng(Hons), PEng(UK),

MASME(USA), B Bus(Aust),MBA(UK),

IEng(UK), MIIIE(mech), MinstAEA, MFIEA,

MIRTE,MIMI,MSAE,MCIARD, AM,NIJAAR(USA),

AM CATARI(CAN),M.MATA(USA),M.MDATA(USA),

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.