



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR22012771/Any3e2 Date: 16/01/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 5193M	Veh. Inspected	SKQ 5631B
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/12/22/2059	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	21/12/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	MR053REH104520969	Colour	GREY
Odometer	313212 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	PIRELLI	6 mm
L/H Front Tyre	205/55 R16	PIRELLI	6 mm
R/H Rear Tyre	205/55 R16	PIRELLI	6 mm
L/H Rear Tyre	205/55 R16	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	20/12/2022	Inspection Date	22/12/2022
Survey held at	SIN YU SIN WORKSHOP 1 KAKI BUKIT AVE 6 #01-82 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		18 Working Days	