

萬 汽 車 服 務

MILLION AUTO SERVICE

No. 4 Penjuru Place #01-12, 2.8 Penjuru Tech Hub, Singapore 608782
 Website: <http://www.millionauto.com> Email: wendy@millionauto.com
 Tel: 6567 0817, 6264 9091 Fax: 6791 4716
 Reg No: 317413/00-K GST Reg No: M90363176A

2495.61

60.00

1130.00

3685.61

20%

2948.48

L/S - \$2,950.00

Vehicle No : GBE3887M

Model : NISSAN NV350

Chassis No : JN1MC2E26Z0005145

Year : 2015

REPAIR ESTIMATE

S.N.	PARTS REPLACEMENT - LIST ITEM	Qty	Unit Price (\$)	Price (\$)
1	FRONT BUMPER ASSY <i>SCA/</i>	1	\$ 701.30	\$ 701.30
2	FRONT BUMPER BRACKET RH <i>? Xnn</i>	1	\$ 147.00	\$ 147.00 X
3	FRONT RADIATOR GRILLE <i>Xnn</i>	1	\$ 455.00	\$ 455.00 X
4	FRONT CORNER PANEL RH <i>4/</i>	1	\$ 477.80	\$ 477.80
5	FRONT PANEL <i>Xnn</i>	1	\$ 1,208.90	\$ 1,208.90 X
6	HEADLAMP RH <i>30/</i>	1	\$ 390.80	\$ 390.80
7	SIDE MIRROR RH <i>Xnn</i>	1	\$ 321.50	\$ 321.50 X
8	FRONT DOOR ASSY RH <i>4/</i>	1	\$ 1,015.80	\$ 1,015.80
9	FRONT DOOR HINGE RH <i>Xnn</i>	1	\$ 70.60	\$ 70.60 X
10	FRONT DOOR CHECKER RH <i>Xnn</i>	1	\$ 87.80	\$ 87.80 X
11	FRONT DOOR WEATHERSTRIP RH <i>4/</i>	1	\$ 187.40	\$ 187.40
12	FRONT DOOR STEP PANEL GARNISH RH <i>Xnn</i>	1	\$ 78.50	\$ 78.50 X

2772.90

10%

2495.61

Less 10%

Sub Total :

\$ 5,140.20

\$ (514.02)

\$ 4,626.18

PARTS REPLACEMENT - SPECIAL NETT ITEMS

- FRONT DOOR ROV STICKER *4/*
- FRONT BUMPER CLIPS *4/*

60

\$ 30.00

\$ 30.00

Sub Total:

\$ 60.00

LABOUR AND MISCELLANEOUS CHARGES

- LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN AFFECTED AREA AND REPLACE DAMAGE PARTS
- TO PUTTY AND SPRAY PAINTING TO AFFECTED AREA
- TO CONDUCT WHEEL ALIGNMENT
- TO APPLY ANTI RUST PROOFING ON AFFECTED AREA
- TO REMOVE AND TRANSFER FRONT DOOR MECHANISM
- TO CHECK LIGHTING SYSTEM
- TO CHECK AND RESET ALL WIRING FUNCTION
- TO CHECK AND RESET ALL WIRING FUNCTION

Rasul

H/ 90010068

5 days

40

22/12/22 @ 1145

\$ 1,100.00 *500*

\$ 900.00 *500*

\$ 100.00 *Xnn 1130*

\$ 100.00 *40*

\$ 100.00 *60*

\$ 60.00 *30*

\$ 80.00 *Xnn*

\$ 120.00 *Xnn*

Sub Total :

\$ 2,560.00

Resurvey after repair

1. The Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: