

ESTIMATE RC AUTO

Not Authorised
Resony B & Pain
87378.84

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel : 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168K

6 days

SJT 8441 J

Date : 05.01.2022

Quantity	Description/Particular	Unit Price	Amount	
1 PC	REAR BOOTLID 453		Ry 1040	00 ✓
1 PC	REAR BOOTLID RUBBER		Pix/M 110	00 ✓
1 PC	REAR BOOTLID OUTER GANISH		CM 280	00 ✓
4 PCS	REAR WINDSCREEN GLASS RUBBER SEAL@32		M 128	00 ✓
1 PC	REAR WINDSCREEN	Photocopy	900	80 ✓
1 PC	REAR BOOTLID INNER GANISH 270		M/M 460	00 ✓
10 PCS	REAR BUMPER CLIP@5		M 50	00 ✓
1 PC	REAR PANEL		Ry 460	60 ✓
2PCS	REAR LAMP@490		CM 980	00 ✓
2 PCS	REAR BOOTLID REFLECTOR@420 0413-20		CM 840	00 ✓
1 PC	REAR PANEL GANISH		Red 116	00 ✓
1 PC	VEZEL LOGO EMBLEM		M 80	00 ✓
1 PC	HONDA LOGO EMBLEM		M 55	00 ✓
1 PC	REAR BOOTLID LOCK		Red 210	00 ✓
2 PCS	REAR BUMPER SIDE@298		Sm 596	00 X
2 PCS	REAR BUMPER REFLECTOR		Sm 120	00 X
2 PCS	REAR FENDER INNER GANISH@380		Red/Act 760	00 ✓

208

Received the above goods in good order and condition

for RC AUTO

Received by

E.&O.E.

Authorised Signature

ESTIMATE RC AUTO

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel : 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168K

SJT 8441 J

Date : 05.01.2022

[illegible]

Received the above goods in good order and condition for RC AUTO

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Received by

E.&O.E.

Authorised Signature