

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## **Immediate Advice**

To: AXA Insurance Pte Ltd DATE: 05/01/2023

## **Survey details**

| Date of loss        | 25-11-22     |
|---------------------|--------------|
| Date of appointment | 22-11-22     |
| Date of survey      | 22-12-22     |
| Location of survey  | EQBH PTE LTD |

## **Vehicle Details:**

| Claim Type:          | THIRD PARTY |
|----------------------|-------------|
| Vehicle number       | VCC 994     |
| Make and Model       | BMW S1000RR |
| Date of registration | 19-09-18    |
| Excess               |             |
| Market Value         | \$50,000.00 |
| Parf Rebate          | -           |
| Nett Loss            |             |

## Repair details

| Initial Estimate              |               |
|-------------------------------|---------------|
| Proposed/Revised repair cost: |               |
| Parts                         |               |
| "Check items (Estimated)      |               |
| Labour                        |               |
| Total                         |               |
| Lump Sum (Estimated)          |               |
|                               |               |
| Number of days of repair      | 06 days (est) |
|                               |               |
| Remarks:                      |               |

The estimated repair cost of the damaged vehicle is in the region of \$7,000.00-\$8,000.00