

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 30 Dec 2022

Preliminary Advice

Vehicle No	: SNA3717A	Accident Date	: 13/12/2022
Make	: MINI COOPER S	Policy No.	: DMPSNW00265742100
Assignment Date	: 22/12/2022	Excess	: S\$250.00
Date of Inspection	: 29/12/2022	Est. Duration of Repair	: 06
Inspection At	: S & H MOTOR PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,227.81
Revised Amount	:S\$	6,673.96
Check Items (Estimated)	:S\$	3,858.85
Total	:S\$	10,532.81

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	92,000.00
COE / PARF Rebate	:S\$	51,754.00
Salvage Value	:S\$	
Margin for Repair	:S\$	40,246.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.