


ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD  TP  /  S /  TP RES /  OD RES /  EVA /  INV /  MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: \_\_\_\_\_  
 of: \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SMC 4187Z Yr Regn: 02/03/2010  
 Type  M.Car  M.Cycle  Bus  Van  Lorry  Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: NISSAN TEANA 2.0L c.c 1997  
 Colour: MAROOR A/C: Insured / Std / NI / NA  
 Sp. Reading: 227577 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JN1BDUJ32Z0001485 \*  
 Gen. Cond:  Good  Fair  Poor  Burnt  
 Steering:  Inorder  Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  Inorder  Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi:  Nil  S/Rim / STD A/Rim or \_\_\_\_\_



Tyre Size: F: 205/65 R16  
 R: //  
 Tyre Brand:  BS  DUN /  EXNOVA /  GY /  FS /  LIZA /  MIC /  OHTSU /  PIR /  SUMI /  
 TOYO / YOKO or \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \$ \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 4 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 23-12-2022  
 Survey held at \_\_\_\_\_ W/S 2:30PM  
 Des. of Damages  Frt  Rear  O/S  N/S  U/C  Rooftop or \_\_\_\_\_  
 The  U/C Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Finalised LS \$1900, 4 days. (Red \$5107.41, 73%)

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) 28/02 Typist  
 Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 4  
 Resurvey No. of Trip: 1

2) \_\_\_\_\_  
 Report Filed: MER-TP  
 Lump Sum: 1900

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Insp (\$ \_\_\_\_\_)  
 : W/Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
3 + RS. SI	
Photos	
Other:	
TOTAL	