



Kah Motor Co. Sdn. Bhd.
(A Member of Oriental Holdings Berhad)
Body Repair & Paint Centre
6A Mandai Estate
Singapore 729903
Tel : +65 6841 3838
Fax : +65 6362 5015
www.honda.com.sg

M/s: AXA Insurance Singapore Pte Ltd
C/o LKK Auto Consultants Pte Ltd
8 Shenton Way
#27-01
Singapore 068811

Date : 8/3/2023

Attn: Motor Claims Department

Ms Hsiao Tong

Your ref : CC4/ASM22012802

Our ref : SLU4659X

Dear Sir / Madam,

THIRD PARTY DIRECT SETTLEMENT

ACCIDENT INVOLVING SLU4659X & SHC1282K DOA: 20/12/2022

We refer to the item(s) marked (☒) below:

- (☒) We refer to your email date 23/12/2022.
- (☒) We enclosed herewith the repair invoice / Third Party Direct Settlement Agreement.
- (☐) Kindly forward the discharge voucher for our client's signature within **2 weeks** via email to : **desmondtoh@honda.com.sg**
- (☒) We return your discharge voucher duly completed.
- (☒) Kindly expedite settlement the following :-

Repair Cost **S\$ 14,207.55** payable to **Kah Motor Co. Sdn. Bhd.**

- (☒) Kindly let us have your cheque made in favour of the above mentioned name(s) for our transmission as soon as possible.
- (☒) Letter of Authority

Thank you.

Yours faithfully,


Anikka Lai


LETTER OF AUTHORITY

TO WHOM IT MAY CONCERN

ACCIDENT INVOLVING (OWNER VEHICLE NO.) SLU4659X &
(THIR PARTY'S VEHICLE NO.) SHC1282K ON 20/12/2022
ALONG AYE (TUAS) @ 16.5KM

I hereby authorize Kah Motor Co. Sdn Bhd (Kah Motor) and its agents or any person authorized by Kah Motor to do all or any of the following:

- To submit, resolve and make any claim(s) which I may have against the 3rd party insurers.
- To execute, sign discharge voucher/indemnity forms and all necessary documents in connection with and arising out of the above claim.
- Any payment should be made in favour of my name / Kah Motor Co. Sdn Bhd.



Owner Signature
(Co stamp & authorized signature if is Co registered vehicle)

Name : ZHANG BINGQI

Nric No : S2729610F

Veh No: SLU4659X

Date : 23/12/2022

WITHOUT PREJUDICE to:

Any Personal Injury Claims



HSBC Life (Singapore) Pte. Ltd.
10 Marina Boulevard,
Marina Bay Financial Centre Tower 2 #48-01,
Singapore 018983
☎ +65 6880 4888
🌐 www.hsbc.life.com.sg
✉ cc.gi@mail.life.hsbc.com.sg

HSBC Life Third Party Direct Settlement

| | | |
|-------------------------|----------------------|--------------------------------|
| Vehicle No: | SHC 1282K (Insd veh) | Model: HONDA HRV 1.5 LX CVT |
| | SLU 4659X (TP veh) | |
| Date of Accident/ Time: | 20/12/2022 | |

| | | | |
|--|--------------------------------|---|--------------------|
| Repair Estimate | : \$ | 19,931.99 | |
| Final Repair Cost w/GST | : \$ | 14,207.53 | |
| Loss of Use | : \$ | | days at \$ per day |
| Rental (if any) | : \$ | | days at \$ per day |
| LTA / GIA Search Fee | : \$ | | |
| Others: | : \$ | | |
| Final Settlement Sum | : \$ | | |
| Payee Name: KAH MOTOR CO SDN BERHAD | | | |
| Is Third Party Workshop GIA Registered? [<input checked="" type="checkbox"/>] YES [] NO (Kindly indicate below) | | | |
| A) Workshop: | For Non GIA Registered | Agreed Liability _____ (%) | |
| B) | For GIA Registered Workshop: | BOLA Applicable: Yes/ No BOLA Scenario No: <u>27</u> | |
| | BOLA Liability: <u>100</u> (%) | Assessed Liability (*): _____ (%) | |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply. | | | |
| Remarks: | | | |

Note:

1. Please expressly reserve your client's rights if so required in this settlement document.
2. This settlement is on a without prejudice basis and should not construed as an admission of liability on HSBC Life and their client/tortfeasor in any manner whatsoever.
3. HSBC Life reserves their rights under the policy terms & conditions as well as their rights in law.


Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (HSBC Life and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident


KAH MOTOR CO. SDN. BHD.
BODY REPAIR & PAINT CENTRE
SINGAPORE 729905
TEL: 6514 5266 FAX: 6365 1949
Date: 15/03/23


Signature of HSBC Life's surveyor & stamp / representative
Name of HSBC Life's surveyor / Representative:
Date: 16/03/2023


KAH MOTOR CO. SDN. BHD.
BODY REPAIR & PAINT CENTRE
SINGAPORE 729905
TEL: 6514 5266 FAX: 6365 1949
Date: 15/03/23

Internal

**Kah Motor Co. Sdn. Bhd.**

(A Member of Oriental Holdings Berhad)

6A Mandai Estate, SINGAPORE 729903

Mandai Parts Centre

Phone No. : +65 6841 3838 Fax No. :

AXA INSURANCE PTE LTD

MOTOR CLAIMS DEPT

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE, 068811

Customer Code : CU0129734

Service Tax Invoice

GST Reg No. M200050223

Company Ref. No. S60FC1380G

Invoice No. : SINV-BM23000236
Invoice Date : 28/02/23
Order No. : SVO22057700
Reference :
Job Card No. : 14625
Date/Time Received : 21/12/22 / 1:35:40 PM
Licence No. : SLU4659X
Model : HRV LX-SIN CVT YM 2016
Car Chassis No. : JHMRU1830GX203441
Car Engine No. : L15B4533442
Mileage : 110607
Service Advisor : ANIKKA LAI SWEE KAM 1821
Served By : ANIKKALAI
Page : 1

| No. | Description | Qty. | UoM | U. Price | Disc % | Amount | 7% GST Amount | Amount incld GST |
|-----------------|--|------|-------|----------|--------|--------|---------------|------------------|
| | TP DIRECT SETTLEMENT (J/NO:) | | | | | | | |
| | OWNER: ZHABG BINGQI | | | | | | | |
| | OWNER INSURER: SOMPO | | | | | | | |
| | ACC DATE: 20/12/2022 | | | | | | | |
| | SURVEYED BY: KENNETH / LKK | | | | | | | |
| | DATE: 28/12/2022 | | | | | | | |
| | REF NO: CC4/ASM22012802/pa3 | | | | | | | |
| | TP INSURER: AXA | | | | | | | |
| | TP VEH: SHC1282K | | | | | | | |
| 68100-T7A-J20ZZ | TAIL GATE COMP | 1 | Each | 915.90 | 25 | 686.92 | 48.08 | 735.00 |
| 74440-T7A-003 | WEATHERSTRIPTAILGATE | 1 | Each | 105.60 | 25 | 79.20 | 5.54 | 84.74 |
| 75722-T7W-A01 | EMBLEMRR. | 1 | Each | 15.40 | 25 | 11.55 | 0.81 | 12.36 |
| 75725-T8N-T00 | EMBLEM,RR. I-VTEC | 1 | Each | 16.70 | 25 | 12.52 | 0.88 | 13.40 |
| 74940-TZ5-A01 | BUZZER ASSYSMART | 1 | Each | 64.70 | 25 | 48.52 | 3.40 | 51.92 |
| 04715-T7A-900ZZ | FACE,RR.BUMPER | 1 | Each | 484.70 | 25 | 363.52 | 25.45 | 388.97 |
| 91505-TM8-003 | CLIP,BUMPER | 10 | Each | 2.30 | 25 | 17.25 | 1.21 | 18.46 |
| 84640-T7A-J01ZA | LINING ASSYRR.PANEL | 1 | Each | 47.00 | 25 | 35.25 | 2.47 | 37.72 |
| 84550-T7A-J00 | BOX ASSY,CARGO FLOOR | 1 | Each | 142.70 | 25 | 107.02 | 7.49 | 114.51 |
| 66100-T7A-300ZZ | PANEL COMPRR. | 1 | Each | 399.40 | 25 | 299.55 | 20.97 | 320.52 |
| 65513-T7A-300ZZ | STIFFENERRR.JACK UP | 1 | Each | 65.70 | 25 | 49.27 | 3.45 | 52.72 |
| 04655-T7A-310ZZ | PANEL SET,RR.FLOOR | 1 | Each | 723.00 | 25 | 542.25 | 37.96 | 580.21 |
| 18307-T7A-901 | SILENCER COMPEXHUAST | 1 | Each | 507.30 | 25 | 380.47 | 26.63 | 407.10 |
| 18215-TF0-003 | RUBBEREX MOUNTING | 1 | Each | 8.00 | 25 | 6.00 | 0.42 | 6.42 |
| 18215-TF0-911 | RUBBEREX MOUNTING | 1 | Each | 6.00 | 25 | 4.50 | 0.32 | 4.82 |
| 74605-T7A-000 | PLATESILENCER BAFFLE | 1 | Each | 29.30 | 25 | 21.97 | 1.54 | 23.51 |
| BG02R | 1438 REPLACE RR. WINDSCREEN.(N) | 1 | Hours | 650.00 | | 650.00 | 45.50 | 695.50 |
| BOSUN | 1466 SUNDRIES | 1 | Hours | 30.00 | | 30.00 | 2.10 | 32.10 |
| BML02I | 1438 INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N) | 1 | Hours | 150.00 | | 150.00 | 10.50 | 160.50 |
| BA02R | 1438 REMOVE & RENEW REVERSE SENSORS-4 PCS (N) | 1 | Hours | 150.00 | | 150.00 | 10.50 | 160.50 |
| BMI03D | 1438 REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N) | 1 | Hours | 650.00 | | 650.00 | 45.50 | 695.50 |
| BC011R | 1438 REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA | 1 | Hours | 325.00 | | 325.00 | 22.75 | 347.75 |
| BC012R | 1438 RESET VEHICLE SMART ENTRY SYSTEM | 1 | Hours | 325.00 | | 325.00 | 22.75 | 347.75 |
| BKTG02R | 1438 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & | 1 | Hours | 325.00 | | 325.00 | 22.75 | 347.75 |

Printed by ANIKKALAI on 28 Feb 2023 at 10:32:41 AM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).



Service Tax Invoice

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

6A Mandai Estate, SINGAPORE 729903

Mandai Parts Centre

Phone No. : +65 6841 3838 Fax No. :

GST Reg No. M200050223

Company Ref. No. S60FC1380G

AXA INSURANCE PTE LTD
MOTOR CLAIMS DEPT
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE, 068811

Customer Code : CU0129734

Invoice No. : SINV-BM23000236
Invoice Date : 28/02/23
Order No. : SVO22057700
Reference :
Job Card No. : 14625
Date/Time Received : 21/12/22 / 1:35:40 PM
Licence No. : SLU4659X
Model : HRV LX-SIN CVT YM 2016
Car Chassis No. : JHMRU1830GX203441
Car Engine No. : L15B4533442
Mileage : 110607
Service Advisor : ANIKKA LAI SWEE KAM 1821
Served By : ANIKKALAI
Page : 2

| No. | Description | Qty. | UoM | U. Price | Disc % | 7% GST Amount incld | | |
|-----------------|---|------|-------|----------|--------|---------------------|--------|----------|
| | | | | | | Amount | Amount | GST |
| | ALIGN TAILGATE.(N) | | | | | | | |
| BMU30R | 1438 REMOVE & REPLACE EXHAUST SYSTEM.(N) | 1 | Hours | 325.00 | | 325.00 | 22.75 | 347.75 |
| BOJSE | 1438 BODY JOINT SEALANT END PANEL | 1 | Hours | 80.00 | | 80.00 | 5.60 | 85.60 |
| BOJSE | 1438 BODY JOINT SEALANT TAILGATE | 1 | Hours | 80.00 | | 80.00 | 5.60 | 85.60 |
| BOJSE | 1438 BODY JOINT SEALANT FLOOR PANEL | 1 | Hours | 80.00 | | 80.00 | 5.60 | 85.60 |
| BKRP02B | 0671 CUT & RENEW RR FLOOR PANEL.STRAIGHTEN FENDERS ALIG RR CHASSIS INCLUDING FIITTING ON ATTACHMENT ITEMS. | 1 | Hours | 3,900.00 | | 3,900.00 | 273.00 | 4,173.00 |
| BP06R | 1847 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) SUPPLEMENTARY PART | 1 | Hours | 3,120.00 | | 3,120.00 | 218.40 | 3,338.40 |
| 73214-T7J-H01 | RUBBER CR.WINDSHIELD DAMPER | 1 | Each | 19.30 | 25 | 14.47 | 1.01 | 15.48 |
| 73226-SZW-000 | DAMPERSTD 5X5 | 1 | Each | 9.10 | 25 | 6.82 | 0.48 | 7.30 |
| 73254-T7J-H01 | RUBBER CL.WINDSHIELD DAMPER | 1 | Each | 19.30 | 25 | 14.47 | 1.01 | 15.48 |
| 76711-T6A-003 | CAPPIVOT | 1 | Each | 5.20 | 25 | 3.90 | 0.27 | 4.17 |
| 91501-S70-003 | FASTENER BW/SHIELD | 4 | Each | 5.30 | 25 | 15.90 | 1.11 | 17.01 |
| 91502-S70-003 | FASTENER B | 2 | Each | 5.40 | 25 | 8.10 | 0.57 | 8.67 |
| 91536-SS0-J01 | FASTENER AW/SHIELD | 2 | Each | 3.80 | 25 | 5.70 | 0.40 | 6.10 |
| BO-WS-SEALANT | WINDSCREEN SEALANT (N) | 2 | Each | 60.00 | | 120.00 | 8.40 | 128.40 |
| 65770-T7J-H00ZZ | CROSSMEMBER COMPRR.FLOOR RR. | 1 | Each | 158.00 | 25 | 118.50 | 8.30 | 126.80 |
| 91513-T6A-003 | CLIPTAILGATE SPOILER | 9 | Each | 2.60 | 25 | 17.55 | 1.23 | 18.78 |
| 74646-T7A-010 | COVERR R.FLOOR UN | 1 | Each | 129.20 | 25 | 96.90 | 6.78 | 103.68 |

| | | | |
|---------------------|-----------|--------|-----------|
| Sum Labor | 10,190.00 | 713.30 | 10,903.30 |
| Sum Item | 3,088.07 | 216.18 | 3,304.25 |
| Total SGD | 13,278.07 | 929.48 | 14,207.55 |
| Total Payable (SGD) | | | 14,207.55 |

Printed by ANIKKALAI on 28 Feb 2023 at 10:32:41 AM

This is a computer generated invoice. No signature is required. Please review your bill and advise us of any errors or omissions.

Kah Motor reserves the right to deliver a subsequent bill for any charge omitted. GST Amount is calculated from individual line(s).