

# PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699  
 Tel: 6366 2323 Fax: 6841 1183  
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Supplementary Estimate

*Xiao Chu*

GST Reg No. 19-9902271-W

<b>AIG Asia Pacific Insurance Pte Ltd</b> 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		<b>Estimate No.</b> PA/OD/1140/2022/EQ <b>Date</b> 17-Jan-23 <b>Service Advisor</b> CHANG <b>Pages</b> 1 of 1 <b>Regn No</b> SNG 3856 A <b>Model No</b> AUDI A4 2.0 TFSI	
Quantity	Description	Unit Price	Amount
<b>Labours</b>			
1	TO DISMANTLE AND RENEW LH FRONT WISHBONE LINK. S/N	\$ 280.00	✓
<b>Parts</b>			
1	FRONT WISHBONE LINK - LH <i>let</i>	\$ 605.00	✓
<b>GRAND TOTAL</b>		<b>\$ 885.00</b>	

For Premium Automobiles Pte Ltd



Authorised Signature

*Adrian Ling*  
*Resumeyed!*

*Add 3 days for the  
 Replacement of the lock  
 carrier.*



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNG 3856 A**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,400.00	✓
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,200.00	✓
5	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ <del>3,500.00</del>	500 + 1250
6	TO RESPRAY FRONT BUMPER.	\$ 900.00	550
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 8,022.00</b>	

\* Additional 3 working days.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNG 3856 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN BRACKET - LH <i>new</i>	1	\$ 33.00	<i>x</i>
22	FRONT PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	\$ 532.00	<i>x</i>
23	FRONT PARKING AID SEAL RING <i>new</i>	4	\$ 10.00	<i>x</i>
24	FRONT BUMPER WIRING SET	1	\$ 642.00	<i>x</i>
25	HEADLIGHT - LH <i>new</i>	1	\$ 8,172.00	<i>x</i>
26	LIFT CYLINDER - LH <i>new</i>	1	\$ 231.00	<i>x</i>
27	LIFT CYLINDER BRACKET <i>new</i>	1	\$ 7.00	<i>x</i>
28	LIFT CYLINDER CORRUGATED PIPE <i>damaged</i>	1	\$ 107.00	<i>✓</i>
29	LOCK CARRIER <i>cracked</i>	1	\$ 1,478.00	<i>2 ✓</i> <i>sls.</i>
30	LOCK CARRIER SUPPORT <i>damaged</i>	1	\$ 43.00	<i>1 ✓</i> <i>sls.</i>
31	CHARGE AIR COOLER <i>damaged</i>	1	\$ 654.00	<i>✓</i>
32	CHARGE AIR COOLER PRESSURE PIPE - LH <i>new</i>	1	\$ 496.00	<i>x</i>
33	A/C CONDENSER <i>?</i>	1	\$ 683.00	<i>?</i>
34	A/C CONDENSER REFRIGERANT LINE <i>new</i>	1	\$ 186.00	<i>x</i>
35	A/C CONDENSER REFRIGERANT LINE <i>new</i>	1	\$ 381.00	<i>x</i>
36	A/C CONDENSER REFRIGERANT LINE <i>new</i>	1	\$ 277.00	<i>x</i>
37	OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>	1	\$ 21.00	<i>x</i>
38	RADIATOR <i>damaged</i>	1	\$ 699.00	<i>2 ✓</i>
39	READY-MIX COOLANT <i>new</i>	6	\$ 297.00	<i>2 ✓</i> <i>sls.</i>
40	RADIATOR AIR GUIDE - LH INNER <i>damaged</i>	1	\$ 51.00	<i>2 ✓</i>
<b>SUB TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 15,000.00</b>	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNG 3856 A**

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
41	RADIATOR AIR GUIDE - LH OUTER	1	\$	19.00	?	
42	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$	44.00	?	
43	FRONT NOISE INSULATION <i>torn</i>	1	\$	640.00	✓	<i>slg.</i>
44	FRONT WHEEL HOUSING LINER -LH <i>new</i>	1	\$	256.00	+	
45	FRONT WHEEL SPOILER - LH <i>new</i>	1	\$	82.00	+	<i>slg.</i>
46	FRONT WHEEL SPOILER END PLATE -LH <i>new</i>	1	\$	39.00	+	
47	FRONT NO PLATE <i>me</i>	S/N	\$	60.00	✓	
48	SUNDRIES		\$	400.00	?	
<b>TOTAL SPARE PARTS</b>		:	\$	<b>24,130.00</b>		
<b>TOTAL LABOUR CHARGES</b>		:	\$	<b>8,022.00</b>		
<b>GRAND TOTAL</b>		:	\$	<b>32,152.00</b>		

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.