

Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 64465
 Date Estimated : 22/12/2022
 Prepared By : Inthiran A/L Thurasamy

Page No. :

- ESTIMATE REPAIR FOR -

Soh Sim Karn
 235 Tembeling Rd
 #04-03

Singapore 423720

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SMW4590L	WBA6V120705N97663	21/11/2019	216i Gran Tourer	29536

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To replace front bumper and attachments, front LH fender and attachments, LH extension wheel housing strut, LH headlight arm support include making good the front LH door and knocking out dents caused by the accident	2,550.00	0.00	2,550.00
* To spray paint front bumper, front LH fender and front LH door	2,668.00	0.00	2,668.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT BUMPER LH INSERT	14.20	1.00	0.00	14.20 <i>de</i>
# FRT LH SIDE PANEL TOP MOUNTING	18.90	1.00	0.00	18.90 <i>de</i>
# EXPANDING RIVET	0.45	4.00	0.00	1.80 <i>wp</i>
# FRT LH FENDER SEALING	34.55	1.00	0.00	34.55 <i>wp</i>
# LH HEADLIGHT LED TECHNOLOGY	2,399.10	1.00	0.00	2,399.10 <i>one</i>

SUPPLEMENTARY ITEMS

Total Labour :	5,218.00
Total Parts :	2,468.55
Total Labour & Parts (before GST) :	7,686.55

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269
 Co Reg No. 197401559W

