

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jenny Lew

Date: 27 Dec 2022

Preliminary Advice

Vehicle No	: SNH8716H	Accident Date	: 19/12/2022
Make	: MERCEDES-BENZ CLA250 AMG A	Policy No.	: DMHCSNW00023232200
Assignment Date	: 23/12/2022	Excess	: S\$2,500.00
Date of Inspection	: 23/12/2022	Est. Duration of Repair	: 6
Inspection At	: AUTO INSURE PTE LTD (HQ) (WOODLANDS) 6 MARSILING LANE SINGAPORE 739145		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,580.95
Revised Amount	:S\$	5,275.95
Check Items (Estimated)	:S\$	1,645.00
Total	:S\$	6,920.95
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	253,000.00
COE / PARF Rebate	:S\$	150,383.00
Salvage Value	:S\$	
Margin for Repair	:S\$	102,617.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.