



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581			Ref: CS/FCI22012820/Uny3m4 Date: 30/12/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMB 3017T	Veh. Inspected	SGG 8525E	
Policy No.	D-22099187MFBP	Coverage (\$)	0.00	
Claim No.	D22004047MFBP	Excess (\$)	0.00	
Assign From	JOANNE TAN JO ANN	Assign Date	23/12/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PICNIC (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JTEGH23B000021698	Colour	BLUE	
Odometer	273257 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	ACHILLES	7 mm	
L/H Front Tyre	215/60 R16	ACHILLES	7 mm	
R/H Rear Tyre	215/60 R16	ACHILLES	7 mm	
L/H Rear Tyre	215/60 R16	ACHILLES	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/12/2022	Inspection Date	23/12/2022	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		