



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD			Ref:	CS3/SMR22011460/Tny3m4-1
60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Date:	05/01/2023
			Code:	SMR
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5616K	Veh. Inspected	SMA 451Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/11/22/2016	Excess (\$)	0.00
	Assign From	ANA	Assign Date	21/12/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA JAZZ 1.3	c.c	1318
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JHMGK3850JX220753	Colour	GREY
	Odometer	36785 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	FALKEN	6 mm
	L/H Front Tyre	185/60 R15	FALKEN	6 mm
	R/H Rear Tyre	185/60 R15	FALKEN	6 mm
	L/H Rear Tyre	185/60 R15	FALKEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT & REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/11/2022	Inspection Date	16/11/2022
	Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	