

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLV 2073T

at Workshop m/s SMU

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$3000

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: \$72k

IDAC Accident Rpt: _____ Consistent?: **Yes** or No

GIA / PR Seen: _____ Consistent?: **Yes** or No

Est. Repairs: 8 days Res.: **Yes** or No

Lum Sum: 30 % 3 Val.: **Yes** or No

CA / REV / REP. / 24 HRS

998h

Vehicle: **IN / OUT**

Date: _____ Person Contacted: LTA @ 40601

Veh No: SLV 2073T Yr Regn: 26/02/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Mercedes c.c. 1998

Colour: Red A/C: **Insured / Std / NI / NA**

Sp. Reading: 179416 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: JM6CW1071H0126678

Gen. Cond: **Good** / Fair / Poor / Burnt

Steering: **Inorder** / Jammed / Leaked / Burnt or affected

Brake: **Inorder** / Jammed / Leaked / Burnt or

Modi: **Nil** / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: 205/55-R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 6 mm Rear R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 18/12/22 D.O.I. 27/12/22

Survey held at _____

Des. of Damages: **Frt / Rear / O/S / N/S / UIC / Rooftop** or

The UIC Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Rep 13/12

9/3/23 4/5 @ 7650 indurnd AH ying @ 08 days (Red \$12,175.60/61%)

Date/Time, File Pass to?

10/03/2023

1) Typist

Date/Time, File Return to?

2) _____

: Preli. Report

: Final Report

Days Of Repair: 08

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

____ S + RS, ____ SI

) Photos

) Others

TOTAL

Report Format : OD

Lump Sum / I.B.I: (\$ L/S \$7,650)

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883
 Tel: 6747 6106 (6 Lines) Fax: 6744 2368
 Email: service@smemotor.com.sg Website: www.smemotor.com.sg
 Co. & GST Reg. No: 201119451E

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	22/AL/OD-640(12)
Policy No:	SP2003638569	Date of Loss:	18/12/2022
Vehicle Reg. No.:	SLV2073T	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	VALIANT KHONG FARN BING		
Driver:	VALIANT KHONG FARN BING		
Make/Model:	MAZDA 5, 2.0 (A)	Vehicle Reg. Date:	26/12/2017
Vehicle Colour:	RED	Chassis No:	JM6CW1071H0126678
Engine No:	PE10527205		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Remarks:	VEHICLE IN, KINLDY ARRANGE FOR SURVEY.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	15,120.60
Miscellaneous Items	275.00
Labour	4,430.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	19,825.60
+ GST 7.00% (S\$)	1,387.79
Nett Amount (S\$)	21,213.39

This claim is handled by: WEN YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

not authorized
 here
 nearby
 Excess \$3000
 vehicle after repair
 2/5 # 7650
 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Dec 2022)
Parts: M1-MPV MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLV2073T)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>SUC</i>	0.00	0.00	*580.00 F <i> </i>
2	1		*FRT BONNET SEAL (WITH CLIPS) <i>TM</i>	0.00	0.00	*55.00 F
3	1		*FRT BONNET INSULATOR <i>11</i>	0.00	0.00	*135.00 F <i>X</i>
4	8		*INSULATOR CLIPS <i>per</i>	0.00	0.00	*20.00 F <i> </i>
5	2		*FRT BONNET HINGE <i>per</i>	0.00	0.00	*90.00 F <i> </i>
6	1		*FRT BONNET LOCK <i>TM</i>	0.00	0.00	*115.00 F <i> </i>
7	1		*FRT BUMPER <i>DIJ</i>	0.00	0.00	*480.00 F <i> </i>
8	2		*FRT BUMPER RETAINER <i>one/mc</i>	0.00	0.00	*50.00 F <i> </i>
9	10		*FRT BUMPER CLIPS <i>11</i>	0.00	0.00	*25.00 F <i> </i>
10	1		*FRT BUMPER INNER SPONGE <i>11</i>	0.00	0.00	*105.00 F <i>X</i>
11	1		*FRT BUMPER REINFORCEMENT <i>11</i>	0.00	0.00	*350.00 F <i>X</i>
12	1		*FRT BUMPER INNER BASE TOP <i>11</i>	0.00	0.00	*220.00 F <i>X</i>
13	1		*FRT BUMPER LOGO <i>11</i>	0.00	0.00	*45.00 F <i>X</i>
14	1		*FRT BUMPER CTR GRILLE <i>11</i>	0.00	0.00	*380.00 F <i>X</i>
15	1		*FOG LAMP LH <i>11</i>	0.00	0.00	*180.00 F <i>X</i>
16	1		*FOG LAMP GARNISH LH <i>11</i>	0.00	0.00	*55.00 F <i>X</i>
17	2		*HEADLAMP <i>11/320</i> <i>o/suc</i>	0.00	0.00	*1,360.00 F <i>17c</i>
18	2		*HEADLAMP LOWER BRACKET <i>11/320</i> <i>o/suc</i>	0.00	0.00	*90.00 F <i>52c</i>
19	1		*HEADLAMP SUPPORT PANEL <i>11</i>	0.00	0.00	*380.00 F <i>X</i>
20	1		*BRACE PANEL <i>11</i>	0.00	0.00	*38.00 F <i>X</i>
21	1		*AIRCON CONDENSER <i>11</i>	0.00	0.00	*480.00 F <i>X</i>
22	1		*RADIATOR <i>11</i>	0.00	0.00	*500.00 F <i>X</i>
23	1		*RADIATOR FAN ASSY <i>11</i>	0.00	0.00	*680.00 F <i>X</i>
24	1		*AIR DUCT <i>11</i>	0.00	0.00	*115.00 F <i>X</i>
25	1		*AIR CLEANER BOX ASSY <i>11</i>	0.00	0.00	*225.00 F <i>X</i>
26	1		*ISTOP CONTROL UNIT RH (CONVERTER) <i>11</i>	0.00	0.00	*420.00 F <i>X</i>
27	1		*FRT FENDER LH <i>11</i>	0.00	0.00	*235.00 F <i>X</i>
28	1		*FRT FENDER INNER COWLING LH <i>11</i>	0.00	0.00	*195.00 F <i>X</i>
29	10		*INNER COWLING CLIPS <i>11</i>	0.00	0.00	*20.00 F <i>X</i>
30	1		*FRT BUMPER UNDER COVER <i>11</i>	0.00	0.00	*195.00 F <i>X</i>
31	1		*FRT FENDER TOP CORNER GARNISH LH <i>11</i>	0.00	0.00	*40.00 F <i>X</i>
32	1		*SIDE SKIRT LH <i>11</i>	0.00	0.00	*580.00 F <i>X</i>
33	15		*SIDE SKIRT CLIPS <i>11</i>	0.00	0.00	*75.00 F <i>X</i>
34	1		*WIPPER GARNISH LH <i>11</i>	0.00	0.00	*130.00 F <i>X</i>
35	1		*WPPER CORNER GARNISH LH <i>11</i>	0.00	0.00	*28.00 F <i>X</i>
36	1		*FRT SHOCK ABSORBER LH <i>11</i>	0.00	0.00	*350.00 F <i>X</i>
37	1		*FRT KNUCKLE ARM LH <i>11</i>	0.00	0.00	*280.00 F <i>X</i>
38	1		*FRT KNUCKLE BEARING LH <i>11</i>	0.00	0.00	*115.00 F <i>X</i>
39	1		*FRT LOWER ARM LH <i>11</i>	0.00	0.00	*210.00 F <i>X</i>
40	1		*FRT ANTI ROLL BAR LINK LH <i>11</i>	0.00	0.00	*95.00 F <i>X</i>
41	1		*FRT RACK END LH <i>11</i>	0.00	0.00	*115.00 F <i>X</i>
42	1		*FRT TIE ROD END LH <i>11</i>	0.00	0.00	*115.00 F <i>X</i>
43	1		*STEERING RACK <i>11</i>	0.00	0.00	*850.00 F <i>X</i>
44	1		*STEERING CROSSMEMBER <i>11</i>	0.00	0.00	*1,750.00 F <i>X</i>
45	1		*FRT LH SPORT RIM (ORI) <i>11</i>	0.00	0.00	*580.00 F <i>X</i>
46	1		*LH ENGINE MOUNTING <i>11</i>	0.00	0.00	*185.00 F <i>X</i>
47	1		*RH ENGINE MOUNTING <i>11</i>	0.00	0.00	*210.00 F <i>X</i>
48	1		*REAR ENGINE MOUNTING <i>11</i>	0.00	0.00	*120.00 F <i>X</i>
49	4		*AUTO OIL <i>11</i>	0.00	0.00	*100.00 F <i>X</i>

F=Franchise part.

Sub Total (S\$) **13,746.00**
 + Margin on L,N Items 10.00% (S\$) **1,374.60**
Total Parts (S\$) **15,120.60**

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	FRT LH TYRE <i>SN</i>	235.00 <i>X</i>
2	1	FRT NUMBER PLATE <i>BAD</i>	40.00 <i>35</i>
Sub Total (S\$)			275.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	30.00 <i>20</i>
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 <i>✓</i>
3	REMOVE & REFIX FRT UNDERCARRIAGE (WITH STEERING RACK)	New	350.00 <i>150</i>
4	REMOVE & REFIX 1 SET ENGINE MOUNTING	New	180.00 <i>2</i>
5	REMOVE & REFIX ENGINE	New	350.00 <i>17 X</i>
6	4 WHEEL ALIGNMENT	New	100.00 <i>70</i>
7	REPROGRAMME ISTOP CONTROL UNIT	New	500.00 <i>11 X</i>
8	REMOVE & REFIX FUSE BOX LH	New	120.00 <i>11 X</i>
9	LABOUR CHARGE	New	1,400.00 <i>800</i>
10	SPRAY PAINTING	New	1,300.00 <i>800</i>
Gross Labour Cost (S\$)			4,430.00

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >

P-7893
+ 102
8682.30
35
2220
10957.1
302
7656

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Dec 2022)
 Parts: M1-MPV MAZDA 5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLV2073T)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>bul</i>	0.00	0.00	*580.00 F
2	1		*FRT BONNET SEAL (WITH CLIPS) <i>TM</i>	0.00	0.00	*55.00 F
3	1		*FRT BONNET INSULATOR <i>an</i>	0.00	0.00	*135.00 F
4	8		*INSULATOR CLIPS <i>an</i>	0.00	0.00	*20.00 F
5	2		*FRT BONNET HINGE <i>an</i>	0.00	0.00	*90.00 F
6	1		*FRT BONNET LOCK <i>TM</i>	0.00	0.00	*115.00 F
7	1		*FRT BUMPER <i>DI</i>	0.00	0.00	*480.00 F
8	2		*FRT BUMPER RETAINER <i>an</i>	0.00	0.00	*50.00 F
9	10		*FRT BUMPER CLIPS <i>an</i>	0.00	0.00	*25.00 F
10	1		*FRT BUMPER INNER SPONGE <i>an</i>	0.00	0.00	*105.00 F
11	1		*FRT BUMPER REINFORCEMENT <i>BD</i>	0.00	0.00	*350.00 F
12	1		*FRT BUMPER INNER BASE TOP	0.00	0.00	*220.00 F
13	1		*FRT BUMPER LOGO <i>an</i>	0.00	0.00	*45.00 F
14	1		*FRT BUMPER CTR GRILLE <i>TM</i>	0.00	0.00	*380.00 F
15	1		*FOG LAMP LH	0.00	0.00	*180.00 F
16	1		*FOG LAMP GARNISH LH <i>TM</i>	0.00	0.00	*55.00 F
17	2		*HEADLAMP <i>n/s 0157</i>	0.00	0.00	*1,360.00 F
18	2		*HEADLAMP LOWER BRACKET <i>n/s 0157</i>	0.00	0.00	*90.00 F
19	1		*HEADLAMP SUPPORT PANEL <i>ere</i>	0.00	0.00	*380.00 F
20	1		*BRACE PANEL	0.00	0.00	*38.00 F
21	1		*AIRCON CONDENSER	0.00	0.00	*480.00 F
22	1		*RADIATOR	0.00	0.00	*500.00 F
23	1		*RADIATOR FAN ASSY	0.00	0.00	*680.00 F
24	1		*AIR DUCT <i>an</i>	0.00	0.00	*115.00 F
25	1		*AIR CLEANER BOX ASSY	0.00	0.00	*225.00 F
26	1		*ISTOP CONTROL UNIT LH (CONVERTER)	0.00	0.00	*420.00 F
27	1		*FRT FENDER LH <i>bul</i>	0.00	0.00	*235.00 F
28	1		*FRT FENDER INNER COWLING LH <i>an</i>	0.00	0.00	*195.00 F
29	10		*INNER COWLING CLIPS <i>an</i>	0.00	0.00	*20.00 F
30	1		*FRT BUMPER UNDER COVER	0.00	0.00	*195.00 F
31	1		*FRT FENDER TOP CORNER GARNISH LH <i>an</i>	0.00	0.00	*40.00 F
32	1		*SIDE SKIRT LH <i>an</i>	0.00	0.00	*580.00 F
33	15		*SIDE SKIRT CLIPS <i>an</i>	0.00	0.00	*75.00 F
34	1		*WIPPER GARNISH LH <i>an</i>	0.00	0.00	*130.00 F
35	1		*WPPER CORNER GARNISH LH <i>TM</i>	0.00	0.00	*28.00 F
36	1		*FRT SHOCK ABSORBER LH	0.00	0.00	*350.00 F
37	1		*FRT KNUCKLE ARM LH	0.00	0.00	*280.00 F
38	1		*FRT KNUCKLE BEARING LH	0.00	0.00	*115.00 F
39	1		*FRT LOWER ARM LH	0.00	0.00	*210.00 F
40	1		*FRT ANTI ROLL BAR LINK LH	0.00	0.00	*95.00 F
41	1		*FRT RACK END LH	0.00	0.00	*115.00 F
42	1		*FRT TIE ROD END LH	0.00	0.00	*115.00 F
43	1		*STEERING RACK <i>an</i>	0.00	0.00	*850.00 F
44	1		*STEERING CROSSMEMBER <i>an</i>	0.00	0.00	*1,750.00 F
45	1		*FRT LH SPORT RIM (ORI) <i>wagal</i>	0.00	0.00	*580.00 F
46	1		*LH ENGINE MOUNTING	0.00	0.00	*185.00 F
47	1		*RH ENGINE MOUNTING	0.00	0.00	*210.00 F
48	1		*REAR ENGINE MOUNTING	0.00	0.00	*120.00 F
49	4		*AUTO OIL	0.00	0.00	*100.00 F

F=Franchise part.

Sub Total (\$\$) **7893** 13,746.00
 + Margin on L,N Items 10.00% (\$\$) 1,374.60
Total Parts (\$\$) 15,120.60

Amir
Amir for blade

81682-30

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

No	Qty	Particulars	Amount
1	1	FRT LH TYRE <i>SL</i>	235.00 <i>X</i>
2	1	FRT NUMBER PLATE <i>BAD</i>	40.00 <i>35</i>
Sub Total (S\$)			275.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

No	Particulars	Lab.Type	Amount
1	WIRE CHECKING	New	30.00 <i>20</i>
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 <i>✓</i>
3	REMOVE & REFIX FRT UNDERCARRIAGE (WITH STEERING RACK)	New	350.00 <i>150</i>
4	REMOVE & REFIX 1 SET ENGINE MOUNTING	New	180.00 <i>7</i>
5	REMOVE & REFIX ENGINE	New	350.00 <i>2</i>
6	4 WHEEL ALIGNMENT	New	100.00 <i>70</i>
7	REPROGRAMME ISTOP CONTROL UNIT	New	500.00 <i>7</i>
8	REMOVE & REFIX FUSE BOX LH	New	120.00 <i>7</i>
9	LABOUR CHARGE	New	1,400.00 <i>800</i>
10	SPRAY PAINTING	New	1,300.00 <i>800</i>
Gross Labour Cost (S\$)			4,430.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

2220

< END OF ESTIMATES >

Total 10,937.3

- 309

Us 7,650

21/03/23

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	23/12/2022 12:11 (SGT)
Reported by	Both
Date of Accident	18/12/2022 22:50 (SGT)
Exact Location of Accident	Adam Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLV2073T

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	VALIANT KHONG FARN BING
NRIC No	SXXXX998H
Email Address	VALIANTKHONG@GMAIL.COM
Mobile Phone No	(Phone) +65-89214258
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mazda
Model	5
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private hire
Transmission	Auto
CC	2000

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2003638569

DRIVER

Name of Driver	VALIANT KHONG FARN BING
NRIC No	SXXXX998H
Date Of Birth	16/03/1978
Occupation	Indoor

Date Of Driving Pass	01/08/2002
Driving experience	20 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-89214258
Alt. Phone Number	-
Email Address	VALIANTKHONG@GMAIL.COM
Address	BLK 104 LORONG 1 TOA PAYOH #01-243
Address complement	-
Postcode	310104
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	PASSENGER
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT NO.T/20221221/7056.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	VALIANT KHONG FARN BING
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SLV2073T
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	Yes

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


30

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



Describe Circumstances of the Accident

Return to Police Station.

I was blocked out and was taken to the
hospital by ambulance ~~and~~ after the accident.
Hence I did not manage to take down
volume B reg plate no.

Declaration

I/we declare the foregoing particulars are true in every respect

36

Printed name of signatory (Name & Title)

Printed name of signatory (Name & Title)

Printed name of signatory (Name & Title)



**SINGAPORE
POLICE FORCE**



T/20221221/7056

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20221221/7056

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/12/2022 20:09	Vide Report No.: E/20221218/0189	Station Diary No.:
--	-------------------------------------	--------------------

Informant's Particulars

Name of Informant: VALIANT KHONG FARN BING		Address: APT BLK 104 LORONG 1 TOA PAYOH #01-243 SINGAPORE 310104	
ID Type / ID No.: NRIC NO / S7806998H		Contact No.: Home/Office: Mobile: 89214258	
Nationality: SINGAPORE CITIZEN		Email: valiantkhong@gmail.com	
Sex: Male	Age: 44	Date of Birth: 16/03/1978	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation:		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 18/12/2022 22:50	Type of Location: Straight Road
Location: ADAM ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 70 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SLV2073T	Car	MAZDA	MAZDA5 WAGON 2.0 AT EU6	Red		0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLV2073T	ALLIANZ INSURANCE SINGAPORE PTE. LTD.	SP2003638569	28/11/2022	27/11/2023



SINGAPORE
POLICE FORCE



T/20221221/7056

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20221221/7056

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	VALIANT KHONG FARN BING	ID No.	S7806998H
Related Vehicle	SLV2073T (Car)	Contact No.	89214258
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	19/12/2022	Date	21/12/2022
No. of Days granted Medical Leave	32	Degree of	Serious

Brief Details.

I was driving along Adam road just exited from PIE, just before the turn to The Japanese Association, i was unable to brake in time and collided into the car in front.



SINGAPORE
POLICE FORCE



T/20221221/7056

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20221221/7056

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPIB /
MUHAMMAD AFIQ BIN RAHMAT
Contact No.: 65476171

Signature Of Informant:
The identity of the person making this report has
been authenticated by Singpass. No signature is
required.

Date/Time:
21/12/2022 20:09

Classification Of Case:

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	998H
Vehicle Details	
Vehicle No.:	SLV2073T
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Dec 2022
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 WAGON 2.0 AT EU6
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	PE10527205
Chassis No.:	JM6CW1071H0126678
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$17,074.00
Original Registration Date:	26 Dec 2017
First Registration Date:	26 Dec 2017
Transfer Count:	1
Actual ARF Paid:	\$17,074.00 <i>8537</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Dec 2027
PARF Rebate Amount:	\$11,951.00
Intended COE Rebate Details	
COE Expiry Date:	25 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,390.00
COE Rebate Amount:	\$28,650.00
Total Rebate Amount:	\$40,601.00

The information contained herein is correct as at 27 Dec 2022

OK

Post an Advertisement
 Sell it yourself! Advertise it at just
\$68 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Subaru Forester 2.0A XT Sunroof.



2nd Car Used By The Mrs.
 Selling Due To Relocation. Only
 Serviced In Subaru.
 Direct Owner StarAd

PRIME MOTOR & LEASING

(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Sort by Date Posted 20 results/page

12 vehicles



mazda 5

Any Category

Advanced Search

Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
mazda 5		Any	Any	2017	Any	Any	Any	Available
	Mazda 5 2.0A Sunroof	\$74,800	\$13,310 /yr	18-Dec-2017	1,998 cc	130,000 km	MPV	Available
Service By Mazda Agent! Very Well Maintained By Previous Owner, Accident Free And In Pristine Condition, 100% In House Loan And Ba... Motor Universe Credit Pte Ltd Posted: 24-Dec-2022								
	Mazda 5 2.0A	\$80,000	\$14,350 /yr	18-Dec-2017	1,998 cc	57,000 km	MPV	Available
Pearl white, beautiful original condition like new. Shelter parked. Family 2nd car. Used only to fetch children. New road tax. Posted: 21-Dec-2022								
	Mazda 5 2.0A Sunroof	\$73,800	\$14,010 /yr	21-Aug-2017	1,998 cc	80,000 km	MPV	Available
Full loan available at \$1581, hassle free transaction with easy financing. 100% accident free, STA/Vicom evaluation welcomed! Contact... Hua Yang Credit Pte Ltd Posted: 21-Dec-2022								
	Mazda 5 2.0A Sunroof	\$70,800	\$14,520 /yr	13-Mar-2017	1,998 cc	81,100 km	MPV	Available
One of the best cost efficient and spacious 7 seater MPV with dual sliding door.Pristine condition! No Repairs Needed! Lowest interest ra... Posted: 20-Dec-2022								
	KHY Motors Pte Ltd - Specialist for Mazda Car repair, servicing & maintenance							
KHY Motors strives to provide great customer service and great prices for all our customers! More info about this shop								
	Mazda 5 2.0A Sunroof	\$69,800	\$13,180 /yr	17-Aug-2017	1,998 cc	98,000 km	MPV	Available
Pristine condition! 1 owner only! Full service and all wear and tear parts done up at Platinum Motoring in house workshop! 100% loan a... This car comes with 6-mth Sgcarmart Warranty - the best protection for your car. Learn More Platinum Motoring Posted: 18-Dec-2022								
	Mazda 5 2.0A Sunroof	\$73,800	\$13,760 /yr	18-Sep-2017	1,998 cc	105,399 km	MPV	Available
Latest Arrival! 1 Owner,! Carefully driven and maintained by previous owner, 100% accident free, No repairs required, Flexible loan, Call... Horizon Motoring Posted: 18-Dec-2022								
	Mazda 5 2.0A Sunroof	\$70,800	\$13,030 /yr	03-Oct-2017	1,998 cc	87,951 km	MPV	Available
Sporty white with premium black interior Mazda 5 Sunroof. Spacious 2.0L MPV suitable for both work and family use, comfortable 7 seat... Posted: 16-Dec-2022								

Compare