

Munich Autocare Pte Ltd (Co.Reg.No:201832250M)

60 Jalan Lam Huat, #07-43

Singapore 737869

Tel: 62552288 Fax: 62655388 Email: dennis.deng@munichautocare.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	SP2002451400	Date of Loss:	13/12/2022
Vehicle Reg. No.:	SMU8691M	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	BIS MOTORING PTE LTD		

Make/Model:	OPEL ASTRA ST, 1.6 D TURBO DIESEL (A)	Vehicle Reg. Date:	01/09/2020
Vehicle Colour:	GREEN	Chassis No:	W0VBD8EG8K8058191
Engine No:	A3191549L8GX0277		
Odometer:	225500 KM		

Paint Type:
Total Loss?
Est. Duration of Repair (day)

NO

86

*Not Authorized
Repair B4 paint
Excess \$1500*

Present Location: **MUNICH AUTOCARE PTE LTD (HQ)****COST OF CLAIMS****Amount**

Parts	14,089.68
Miscellaneous Items	175.00
Labour	3,790.00
Paintwork Labour	0.00
Towing	0.00

Calculated Gross Total (S\$)	18,054.68
-------------------------------------	------------------

- Excess (S\$)	2,000.00
-----------------------	-----------------

(S\$)	16,054.68
--------------	------------------

+ GST 7.00% (S\$)	1,123.83
--------------------------	-----------------

Nett Amount (S\$)	17,178.51
--------------------------	------------------

his claim is handled by: **LIM JIA HAW**Generated using **Merlmen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 24 Dec 2022)**Parts:** 144 OPEL ASTRA ST 1.6 D TURBO DIESEL (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Munich Autocare Pte Ltd/SMU8691M/24/12/2022 12:41**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1	39054067	*FRONT BONNET	R 0.00	0.00	*1,023.00 F	✓
2	1	39032149	*FRONT BONNET HINGLE LH	0.00	0.00	*32.00 F	✓
3	1	39032150	*FRONT BONNET HINGLE RH	0.00	0.00	*32.00 F	✓
4	1	39081894	*FRONT HEADLAMP LH	0.00	0.00	*665.60 F	✓
5	1	39081895	*FRONT HEADLAMP RH	CM 0.00	0.00	*665.60 F	✓
6	1	39058200	*FRONT HEADLAMP LOWER BRACKET LH	0.00	0.00	*65.00 F	✓
7	1	39058201	*FRONT HEADLAMP LOWER BRACKET RH	0.00	0.00	*65.00 F	✓
8	1		*FRONT HEADLAMP ABSORBER BRACKET LH	0.00	0.00	*65.00 F	✓
9	1		*FRONT HEADLAMP ABSORBER BRACKET RH	0.00	0.00	*65.00 F	✓
10	1	39086891	*FRONT FENDER BRACKET LH	R 0.00	0.00	*22.40 F	X
11	1	39086892	*FRONT FENDER BRACKET RH	R 0.00	0.00	*22.40 F	X
12	1	39052728	*FRONT BUMPER	R 0.00	0.00	*1,632.80 F	✓
13	1	39089229	*FRONT RADIATOR GRILLE	CM 0.00	0.00	*400.00 F	✓
14	1	39132771	*FRONT RADIATOR GRILLE INNER BASE	CM 0.00	0.00	*400.00 F	✓
15	1	39086922	*FRONT GRILLE LOGO	CM 0.00	0.00	*109.00 F	✓
16	1	13423641	*FRONT RADIATOR GRILLE MOULDING CHROME LH	0.00	0.00	*166.00 F	✓
17	1	13423642	*FRONT RADIATOR GRILLE MOULDING CHROME RH	0.00	0.00	*166.00 F	✓
18	1	39089220	*FRT LOW CENTRE GRILLE	Dis 0.00	0.00	*138.00 F	✓
19	4	13447589	*FRONT PARKING SENSOR	0.00	0.00	*320.00 F	✓
20	1	39086895	*FRONT BUMPER RETAINER LH	Dis 0.00	0.00	*31.20 F	✓
21	1	39086896	*FRONT BUMPER RETAINER RH	Dis 0.00	0.00	*31.20 F	✓
22	1	39011390	*FRONT FENDER LH	R 0.00	0.00	*442.00 F	X
23	1	39011391	*FRONT FENDER RH	R 0.00	0.00	*442.00 F	X
24	1	13481997	*FRONT BUMPER FOG LAMP COVER LH	R 0.00	0.00	*180.70 F	X
25	1	13481998	*FRONT BUMPER FOG LAMP COVER RH	R 0.00	0.00	*180.70 F	X
26	1	39098907	*FRONT BUMPER FOG LAMP LH	R 0.00	0.00	*295.10 F	X
27	1	39098908	*FRONT BUMPER FOG LAMP RH	R 0.00	0.00	*295.10 F	X
28	1	39179270	*FRONT RADIATOR GRILLE SEAL RH	0.00	0.00	*21.00 F	✓
29	1	39179271	*FRONT RADIATOR GRILLE SEAL LH	0.00	0.00	*21.00 F	✓
30	1	39179263	*FRONT RADIATOR CENTER TOP SEAL	0.00	0.00	*31.00 F	✓
31	1	39015887	*FRT BUMPER SPONGE	0.00	0.00	*188.00 F	✓
32	1	39151027	*FRONT BUMPER REINFORCEMENT LOW (FIRBE)	0.00	0.00	*226.00 F	✓
33	1	39160863	*FRONT BUMPER REINFORCEMENT UPP (METAL)	R 0.00	0.00	*569.00 F	✓
34	1	39052086	*FRONT SUPPORT PANEL	R 0.00	0.00	*172.00 F	✓
35	1	39155356	*FRONT WASHING TANK	R 0.00	0.00	*91.00 F	X
36	1	39185893	*FRONT RADIATOR	0.00	0.00	*846.00 F	✓
37	1	93160377	*FRONT RADIATOR COOLANT	0.00	0.00	*60.00 F	✓
38	1	39013322	*FRONT RADIATOR FAN COWLING WITH MOTOR	0.00	0.00	*1,206.00 F	✓
39	1	39011385	*FRONT AC CONDENSOR	R 0.00	0.00	*815.00 F	✓
40	1	39185909	*FRONT A.T.F COOLER	0.00	0.00	*610.00 F	✓

F=Franchise part.

Sub Total (\$\$) 12,808.80
+ Margin on L,N Items 10.00% (\$\$) 1,280.88

Total Parts (\$\$) 14,089.68

Munich Autocare Pte Ltd/SMU8691M/24/12/2022 12:41. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	10	FENDER INNER SHIELD CLIP LH	nn	70.00	X
2	1	FRONT NUMBER PLATE WITH CASING	B	35.00	✓
3	10	FRONT RADIATOR TOP GARNISH CLIPS	M	70.00	✓

Sub Total (\$\$) 175.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO REMOVE & REFIX, REPAIR, KNOCKING, WELDING FRONT PORTION, BONNET , BUMPER , FENDER LH/RH , SUPPORT PANEL AND DAMAGE AREA	New	60d	1,500.00	
2	TO CHECK ALL WIRING FOR OPERATION AND PARKING SENSOR FOR OPERATION	New	20d	120.00	
3	TO CHECK AND ADJUST HEADLAMP LH/RH FOCUS	New		120.00	
4	TO CONDUCT RE-PROGRAME AIR BAG SYSTEM AND SETTING OF ECU SYSTEM TO CLEAR FAULT CODE	New	7	380.00	
5	TO CONDUCT 4 WHEEL ALIGNMENT AND BALANCING	New	nn	120.00	X
6	TO REMOVE/INSTALL RADIATOR COOLING SYSTEM & ALL NECESSARY PARTS, INCLUDING PRESSURE TEST, BLEED COOLING SYSTEM & CHECK LEAKS AND DAMAGE AREA	New	60d	350.00	
7	TO RESPRAY FRONT PORTION, BONNET INNER / OUTER , BONNET , BUMPER , FENDER LH/RH , SUPPORT PANEL AND DAMAGE AREA	New	800h	1,200.00	

Gross Labour Cost (\$\$) 3,790.00

Munich Autocare Pte Ltd/SMU8691M/24/12/2022 12:41. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: