



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd			
			Document No. 0		3 Media Close #01-03/06 Singapore 138498			
			Document Date 27/12/2022		Work: 65703925			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2022	NHP170R	MWXNB H2	09/11/2022	SNH5684K	0	19323	75/DS/SNH5684K	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDZZ9H380L001119		1NZ9410038	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.: GBD6804M ACC DATE: 24/12/22 DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:						30 100.00
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST						198.00
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME						198.00
4	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN & PANEL BEAT ACC AFF AREA						792 2376.00
5	B	BP-RES2 RESPRAY ACC AFF AREA						656 2824.00
6	1	T52119-5A967 COVER, FR BUMPER <i>repair</i>			1.00	381.60		381.60
7	2	T52125-52070 BRACKET, FOG LAMP <i>X</i>			1.00	58.30		58.30
8	3	T52611-52350 ABSORBER, FR BUMPER <i>X</i>			1.00	96.10		96.10
9	4	T52131-52250 REINFORCEMENT, FR <i>X</i>			1.00	430.30		430.30
10	5	T52161-16010 PIECE, RR BUMPER <i>X</i>			10.00	5.40		54.00
11	6	T53101-52670 GRILLE SUB-ASSY. <i>X</i>			1.00	986.60		986.60
12	7	T81130-52M90 UNIT ASSY, HEADLAMP, <i>sea</i>			1.00	1222.10		1222.10
13	8	T81170-52M90 UNIT ASSY, HEADLAMP, <i>X</i>			1.00	1222.10		1222.10

Paul
Hp 20010068
3 days
05/06/23 P1165
Ready after repair

For & on behalf of		Customer's Signature	Charge Summary		Total
Borneo Motors (Singapore) Pte Ltd					9,947.10
INK AND CONSULTANTS FINANCE notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		Parts	4,451.10	GST 7.00%	696.30
		Labour	5,496.00	Less	0.00
		Sublet	0.00		
		Lubrication/Fluid	0.00		
		Others	0.00	Amount Due	10,643.40

Customer Copy