

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 28 Dec 2022

Preliminary Advice

Vehicle No	: SFN8484P	Accident Date	: 16/12/2022
Make	: AUDI Q7	Policy No.	: 1800053121
Assignment Date	: 28/12/2022	Excess	: S\$0.00
Date of Inspection	: 23/12/2022	Est. Duration of Repair	: 5
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,796.00
Revised Amount	:S\$	20,809.00
Check Items (Estimated)	:S\$	3,199.00
Total	:S\$	24,008.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	175,000.00
COE / PARF Rebate	:S\$	79,725.00
Salvage Value	:S\$	
Margin for Repair	:S\$	95,275.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.