

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Dec 2022)	Lim Tien Siong
Parts: 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: ComfortDelGro Engineering Pte Ltd/SHA4519U/27/12/2022 15:16		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT DOOR RH <i>repair</i>	20.00	0.00	*2,707.70 FL X
2	1		*REAR DOOR RH <i>repair</i>	20.00	0.00	*2,416.80 FL X
3	1		*REAR FENDER RH <i>bt</i>	20.00	0.00	*2,171.40 FL
4	1		*REAR BUMPER <i>Sub</i>	20.00	0.00	*553.00 FL
5	10		*REAR BUMPER CLIPS <i>sub</i>	20.00	0.00	*22.00 FL
6	1		*REAR WHEEL CAP RH <i>de</i>	20.00	0.00	*217.20 FL
7	1		*ROCKER PANEL GARNISH RH <i>de</i>	20.00	0.00	*732.80 FL
8	1		*REAR WHEEL RIM RH <i>repair</i>	20.00	0.00	*325.30 FL XR
9	1		*REAR WESTLAKE TYRE RH <i>XX</i>	0.00	0.00	*216.00 F X
10	1		*FRT DOOR COMFORTDELGRO RH <i>sub</i>	0.00	0.00	*75.00 F
11	1		*REAR DOOR ZIG RH <i>sub</i>	0.00	0.00	*80.00 F
12	1		*REAR WINDSCREEN MOULDING <i>sub</i>	20.00	0.00	*51.80 FL
13	2		*REAR WINDSCREEN SEALANT <i>sub</i>	0.00	0.00	*92.00 F
F=Franchise part, L=ListItemDisc.						
Sub Total (S\$)				3748.20		9,661.00
- List Item Discount on L Items (S\$)				20%		1,839.60
Total Parts (S\$)				2998.56		7,821.40

ComfortDelGro Engineering Pte Ltd/SHA4519U/27/12/2022 15:16. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

* 247

Estimates on Labour

No Particulars

Lim Tien Siong

Labour Items	Lab. Type	Amount
1 PANEL BEATING	New	1120 1200.00
2 SPRAY PAINTING	New	1250 1500.00
3 TUFF KOTE	New	60 200.00
4 TRANSFER DOORS	New	2710 240.00
5 WHEEL ALIGNMENT	New	60 120.00
6 R/I REAR WINDSCREEN	New	120 150.00
7 R/I REVERSE SENSORS	New	40 120.00
8 R/I UPHOLSTERY ETC	New	60 150.00
Gross Labour Cost (S\$)		3,680.00

ComfortDelGro Engineering Pte Ltd/SHA4519U/27/12/2022 15:16. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Sgt. 31

Rasul

Hp 900/100 68

8 days

43

28/12/22 @ 1510

Resurvey after repair

2998.56

247.00

2710.00

5985.56

2026

4764.44

45-84750