

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	22/EG/OD-644 (12)
Policy No:	DMPG22009954	Date of Loss:	24/12/2022
Vehicle Reg. No.:	SKG1080U	Driveable?	
Driver Age/Info:	38 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEE WEI XIN	Contact No:	+6593391909
Driver:	LEE WEI XIN		
Make/Model:	MAZDA CX-9, 2.5 (A)	Vehicle Reg. Date:	14/08/2020
Vehicle Colour:	WHITE		
Engine No:	PY30982559	Chassis No:	JM6TC2WLAK0319839
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Remarks:	VEHICLE NOT IN.		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	13,557.50
Miscellaneous Items	40.00
Labour	1,730.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	15,327.50
+ GST 7.00% (S\$)	1,072.93
Nett Amount (S\$)	16,400.43

This claim is handled by: CHIA PEI YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Dec 2022)
Parts: M1-SUV MAZDA CX-9 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: SME Motor Pte Ltd/SKG1080U/28/12/2022 12:52
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>Dented</i>	0.00	0.00	✓ *650.00 F
2	2		*FRT BONNET HINGE <i>But ✓</i>	0.00	0.00	? *76.00 F
3	1		*FRT BONNET LOCK <i>? X New</i>	0.00	0.00	? *110.00 F
4	1		*FRT GRILLE ASSY <i>could</i>	0.00	0.00	✓ *1,850.00 F
5	1		*FRT GRILLE CENTER LOGO <i>new</i>	0.00	0.00	✓ *75.00 F
6	1		*FRT GRILLE LOGO BASE <i>? X New</i>	0.00	0.00	? *75.00 F
7	1		*FRT GRILLE TOP GARNISH <i>? ✓ Dented</i>	0.00	0.00	? *260.00 F
8	6		*FRT GRILLE TOP GARNISH CLIP <i>? ✓ New</i>	0.00	0.00	? *18.00 F
9	1		*FRT BUMPER <i>Dented</i>	0.00	0.00	✓ *980.00 F
			AGENT			
10	2		*FRT BUMPER RETAINER <i>? X New</i>	0.00	0.00	? *56.00 F
11	10		*FRT BUMPER CLIP <i>new</i>	0.00	0.00	✓ *25.00 F
12	1		*FRT BUMPER INNER SPONGE <i>could</i>	0.00	0.00	✓ *130.00 F
			AGENT			
13	1		*FRT BUMPER REINFORCEMENT <i>? ✓ Dented</i>	0.00	0.00	? *380.00 F
14	1		*FRT BUMPER REINFORCEMENT OUTER GARNISH <i>could.</i>	0.00	0.00	? *195.00 F
			AGENT			
15	1		*NUMBER PLATE GARNISH <i>new ✓ Dented</i>	0.00	0.00	+ *75.00 F
16	2		*HEADLAMP <i>could ✓</i>	0.00	0.00	? *6,900.00 F
17	1		*HEADLAMP SUPPORT PANEL <i>? ✓ But could.</i>	0.00	0.00	? *350.00 F
18	1		*FRT BUMPER TOP BEAM <i>? ✓ Dented</i>	0.00	0.00	? *120.00 F

F=Franchise part.

Sub Total (S\$)	12,325.00
+ Margin on L,N Items 10.00% (S\$)	1,232.50
Total Parts (S\$)	13,557.50

SME Motor Pte Ltd/SKG1080U/28/12/2022 12:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	NUMBER PLATE <i>Best.</i>	40.00 ✓
Sub Total (S\$)			40.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New <i>MS</i> ✓	30.00
2	REMOVE & REFIX AIRCON AND GAS	New <i>MS</i> ✓	100.00
3	LABOUR CHARGE	New <i>MS</i> ✓	700.00
4	SPRAY PAINTING (PEARL)	New <i>MS</i> ✓	900.00
Gross Labour Cost (S\$)			1,730.00

SME Motor Pte Ltd/SKG1080U/28/12/2022 12:52. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Adrian
P/P 29/12/22
06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883
Tel: 6747 6106 (6 Lines) Fax: 6744 2368
Email: service@smemotor.com.sg Website: www.smemotor.com.sg
Co. & GST Reg. No: 201119451E

(SUPPLEMENTARY)

INSURER: ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN.DAMAGE)	Ref. No:	22/EG/OD-644 (12)
Policy No:	DMPG22009954	Date of Loss:	24/12/2022
Vehicle Reg. No.:	SKG1080U	Driveable?	
Driver Age/Info:	38 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEE WEI XIN	Contact No:	+6593391909
Driver:	LEE WEI XIN		
Make/Model:	MAZDA CX-9, 2.5 (A)	Vehicle Reg. Date:	14/08/2020
Vehicle Colour:	WHITE		
Engine No:	PY30982559	Chassis No:	JM6TC2WLAK0319839
Odometer:	54417 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	1,262.80
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,262.80
+ GST 7.00% (S\$)	88.40
Nett Amount (S\$)	1,351.20
+ Previous Estimates (S\$)	16,400.43
Claim Total (S\$)	17,751.63

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 12 Jan 2023)
Parts: M1-SUV **MAZDA CX-9 2.5 (A)** (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: SME Motor Pte Ltd/SKG1080U/12/01/2023 16:00
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	6		*GRILLE TOP GARNISH CLIPS <i>new</i>	0.00	0.00	*33.00 F ✓
2	1		*AIRCON CONDENSER <i>wrapped.</i>	0.00	0.00	*450.00 F ✓
3	1		*SUPPORT TOP GARNISH <i>new.</i>	0.00	0.00	*350.00 F ✓
4	1		*SUPPORT FRT AIR GUIDE <i>behind</i>	0.00	0.00	*125.00 F ✓
5	1		*BRACE PANEL <i>Bent.</i>	0.00	0.00	*95.00 F ✓
6	1		*AIR DUCT <i>behind</i>	0.00	0.00	*95.00 F ✓
Sub Total (\$\$)						1,148.00
+ Margin on L,N Items 10.00% (\$\$)						114.80
Total Parts (\$\$)						1,262.80

F=Franchise part.

SME Motor Pte Ltd/SKG1080U/12/01/2023 16:00. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Admin S.
H.S.