



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR22012927/Gvy3m4 Date: 14/02/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMB 1464Z	Veh. Inspected	PC 2449X
Policy No.		Coverage (\$)	0.00
Claim No.	BUS/12/22/5033	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	28/12/2022
2. Vehicle Particulars & Condition			
Make & Model	MAN A69	c.c	6871
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WMAA69ZZ5DC018672	Colour	RED / GREEN
Odometer	233798 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	5 mm
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	5 mm
R/H Rear Tyre	275/70 R22.5	BRIDGESTONE	5 mm
L/H Rear Tyre	275/70 R22.5	BRIDGESTONE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/12/2022	Inspection Date	28/12/2022
Survey held at	3 TEMASEK BOULEVARD #01-330 SUNTEC SHOPPING MALL		
Repairer	BOXFRESH PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	