



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                 |                            |  |
|--|--|-----------------|----------------------------|--|
| STRIDES AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK<br>E4SINGAPORE 757705  |  |                 | Ref: CS/SMR22012938/Kwy3m4 |  |
|  |  |                 | Date: 20/01/2023           |  |
|  |  |                 | Code: SMR                  |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                 |                            |  |
| Insured Veh.   | SHB 855U   | Veh. Inspected  | SMK 7183Y                  |  |
| Policy No.   |  | Coverage (\$)   | 0.00                       |  |
| Claim No.  | TAX/12/22/2019   | Excess (\$)     | 0.00                       |  |
| Assign From  | HUA YEN  | Assign Date     | 28/12/2022                 |  |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                 |                            |  |
| Make & Model   | TOYOTA PRIUS (A)   | c.c             | 1798                       |  |
| Engine No.   | HIDDEN   | Year of Reg.    | 2019                       |  |
| Chassis No.  | JTDZS3EU60J038809  | Colour          | METALLIC MAROON            |  |
| Odometer   | 330024 KM  | Steering        | IN ORDER                   |  |
| Brakes   | IN ORDER   | Modification    | STANDARD ALLOY RIM         |  |
| General  | GOOD   |                 |                            |  |
| <b>3. Conditions of Tyres</b>  |  |                 |                            |  |
|  | Size   | Make            | Balance                    |  |
| R/H Front Tyre   | 205/60 R15   | FIRENZA         | 7 mm                       |  |
| L/H Front Tyre   | 205/60 R15   | FIRENZA         | 7 mm                       |  |
| R/H Rear Tyre  | 205/60 R15   | FIRENZA         | 7 mm                       |  |
| L/H Rear Tyre  | 205/60 R15   | FIRENZA         | 7 mm                       |  |
| <b>4. Description of Damages</b>   |  |                 |                            |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS.   |  |                 |                            |  |
| <b>5. General Information</b>  |  |                 |                            |  |
| Accident Date  | 06/12/2022   | Inspection Date | 28/12/2022                 |  |
| Survey held at   | MY CAR CONSULTANT PTE LTD<br>60 JALAN LAM HUAT<br>#05-21 CARROS CENTRE<br>SINGAPORE 737869 |                 |                            |  |
| <b>5a. Remarks</b>   |  |                 |                            |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                 |                            |  |
| <b>5b. Estimate Days of Repair</b>   |  |                 |                            |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  |                 | 5 Working Days             |  |