



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

DATE: 20/03/2023

Survey details

| | |
|---------------------|------------------------|
| Date of loss | 24-12-22 |
| Date of appointment | 28-12-22 |
| Date of survey | 28-12-22 |
| Location of survey | ESL AUTOMOTIVE PTE LTD |

Vehicle Details:

| | |
|----------------------|--------------------------------|
| Claim Type: | THIRD PARTY |
| Vehicle number | SGK 3833C |
| Make and Model | OPEL INSIGNIA GRANSPORT B15XHT |
| Date of registration | 29-08-19 |
| Excess | |
| Market Value | \$110,000.00 |
| Parf Rebate | \$48,730.00 |
| Nett Loss | \$61,270.00 |

Repair details

| | |
|------------------|--|
| Initial Estimate | |
|------------------|--|

Proposed/Revised repair cost:

| | |
|--------------------------|---------|
| Parts | |
| "Check items (Estimated) | |
| Labour | |
| Total | |
| Lump Sum (Estimated) | |
| | |
| Number of days of repair | 06 DAYS |

Remarks:

The estimated repair cost of the damaged vehicle is in the region of \$9,000.00-\$10,000.00