

SERVICE ESTIMATE

85763 - C00001 SL: SERVICE SALES - PC
 Mr BS Azmi Bin Saaïd
 21 Jalan Punai

Singapore 418800

Closed by : Juan Paulo Bongon Ba
 Svc Consultant :
 Remarks : Mr Azmi Bin Saaïd

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 29/12/2022
 WIP No. . : 56691
 Veh.In/Out:
 *Tel.No. . : Mobile: 98622930
 Reg.No. . : SLD9905S
 Reg.date . : 01/07/2016
 Mileage .. : 0
 Chassis No: SALCA2AG2GH564495

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE SIDE MIRROR ASSY	0	1500.00	0		1,500.00	S
LH, FRT WINDSCREEN MLDG LH							
800	TO SPRAY RH SIDE MIRROR COVER,	0	2200.00	0		2,200.00	S
RH A PILLAR, RHF DOOR							
280	TO CHECK WIRING INCLUDE	0	621.00	0		621.00	S
RESETTING OF ALL ELECTRICAL							
MODULES							
	MIRROR - REAR VIEW -	1.0 EA	1007.50			1,007.50	S
	COVER - MIRROR HOUSI	1.0 EA	229.20			229.20	S
	LAMP - EXTERIOR MIRR	1.0 EA	214.10			214.10	S
	MIRROR MOTOR LH MEMO	1.0 EA	349.80			349.80	S
	GLASS - REAR VIEW OU	1.0 EA	317.20			317.20	S
	LAMP - EXTERIOR MIRR	1.0 EA	220.60			220.60	S
	MOULDING - DOOR WIND	1.0 EA	355.90			355.90	S
	FINISHER - 'A' PILLA	1.0 EA	231.00			231.00	S

Gross Total. 7,246.30

Labour Total 4,321.00
 Parts Total 2,925.30
 Package Total 0.00

Net..... 7,246.30
 GST @ 7.0% 507.24
 Total..... 7,753.55
 Paid..... 0.00
 Please Pay.. 7,753.55

GST: S=StdRated; O=OutOfScope; Z=ZeroRated