

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ivy Yong

Date: 03 Jan 2023

Preliminary Advice

Vehicle No	: SLT1719G	Accident Date	: 23/12/2022
Make	: MERCEDES-BENZ GLA180 URBAN (R18 LED)	Policy No.	: 0
Assignment Date	: 29/12/2022	Excess	: S\$500.00
Date of Inspection	: 30/12/2022	Est. Duration of Repair	: 4
Inspection At	: MOVA AUTOMOTIVE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,840.93
Revised Amount	:S\$	9,817.90
Check Items (Estimated)	:S\$	2,683.03
Total	:S\$	12,500.93
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	108,000.00
COE / PARF Rebate	:S\$	39,398.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,602.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Part by part repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .