



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



INSURER:

ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	0	Date of Loss:	23/12/2022
Vehicle Reg. No.:	SLT1719G	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHUA SIAK MONG		
Make/Model:	MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A)	Vehicle Reg. Date:	20/10/2017
Vehicle Colour:	GREY	Chassis No:	WDC1569422J422573
Engine No:	27091031413113		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		

Present Location: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)

COST OF CLAIMS**Amount**

Parts	11,310.93
Miscellaneous Items	0.00
Labour	1,530.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	12,840.93
+ GST 7.00% (\$\$)	898.87
Nett Amount (\$\$)	13,739.80

This claim is handled by: ONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Dec 2022)

Parts: M1-SUV MERCEDES-BENZ GLA180 URBAN (R18 LED) 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLT1719G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT HEADLAMP LH <i>ma</i>	0.00	0.00	*3,765.00 F
2	1		*FRONT SUPPORT PANEL	0.00	0.00	*1,248.00 F
3	1		*FRONT SUPPORT PANEL BRACKET LH ?	0.00	0.00	*69.30 F
4	1		*FRONT BUMPER <i>de</i>	0.00	0.00	*2,074.00 F
5	1		*FRONT BUMPER FINISHER COVER LH <i>mis</i>	0.00	0.00	*113.00 F
6	1		*FRONT BUMPER CLIPS <i>ne</i>	0	0.00	*40.00 FS
7	1		*FRONT GRILLE ASSY	0.00	0.00	*392.00 F
8	1		*FRONT GRILLE BASE	0.00	0.00	*443.00 F
9	1		*FRONT BUMPER FINISHER BRACKET LH ?	0.00	0.00	*105.00 F
10	1		*FRONT FENDER LH <i>bt</i>	0.00	0.00	*1,350.00 F
11	1		*FRONT FENDER INNER LINER LH <i>cu</i>	0.00	0.00	*319.00 F
12	1		*FRONT FENDER EXTENSION COVER LH <i>de</i>	0.00	0.00	*368.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	10,286.30
+ Margin on L,N Items 10.00% (\$\$)	1,024.63
Total Parts (\$\$)	11,310.93

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE & REPLACE & REFIT FRONT RADIATOR, AIR COND CONDENSOR & ETC. TO EFFECT REPLACE OF FRONT SUPPORT PANEL	New	80? 100.00
2	TO REMOVE & REPLACE & REFIX & READJUST FRONT ACCIDENT AREA SUCH AS FRONT GRILLE, FRONT BUMPER, FRONT FENDER LH, FRONT HEADLAMP & ETC. BACK TO ORIGINAL CONDITION	New	400 550.00
3	TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER & ETC	New	400.00
4	TO REFILL AIRCOND GAS & VACUUM	New	80? 100.00
5	TO REMOVE & REFIX FRONT BUMPER DISTANCE SENSOR, DISTANCE SENSOR RADAR & ETC. TO EFFECT REPLACE OF FRONT BUMPER	New	60 120.00
6	TO DIAGNOSIS FAULTY CODE & RESET MEMORY	New	100 100.00
7	TO CHECK WIRING & ELECTRICAL SYSTEM	New	30 80.00
Gross Labour Cost (\$\$)			1,530.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 96010068
4 days
P/P
30/12/22 @ 1155
EXCESS: TBA
Revers
Resy before
print