

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Dec 2022)
Parts: 143 BMW 640I 3.0 GRAN COUPE M SPORT LED SR NAV HUD (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SDH681U/29/12/2022 09:33
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRT BUMPER (M SPORTS)	0.00	0.00	*1,800.00 F	DD
2	1		*FRT BUMPER PARKING SENSOR (LH)	0.00	0.00	*180.00 F	MIS
3	1		*FRT BUMPER PARKING SENSOR O RING (LH)	0.00	0.00	*6.00 F	MIS
4	1		*FRT BUMPER HOLDER (LH)	0.00	0.00	*15.00 F	MIS
5	1		*FRT HEADLAMP (LH)	0.00	0.00	*4,500.00 F	CRA
6	1		*FRT HEADLAMP BRACKET (LH)	0.00	0.00	*55.00 F	XNN
7	1		*FRT HEADLAMP NOZZLE (LH)	0.00	0.00	*190.00 F	?
8	1		*FRT HEADLAMP NOZZLE COVER (LH)	0.00	0.00	*60.00 F	?
9	1		*FRT HEADLAMP NOZZLE SPRING (LH)	0.00	0.00	*23.00 F	?
10	1		*FRT FENDER INNERSHIELD (LH)	0.00	0.00	*100.00 F	XNN
11	1		*FRT FOGLAMP (LH)	0.00	0.00	*230.00 F	?
12	1		*FRT FOGLAMP GRILLE	0.00	0.00	*52.00 F	?
13	1		*FRT AIR DUCT (LH)	0.00	0.00	*55.00 F	XNN
14	1		*FRT EMBLEM	0.00	0.00	*80.00 F	NEG

F=Franchise part.

Sub Total (S\$)	7,346.00
+ Margin on L,N Items 10.00% (S\$)	734.60
Total Parts (S\$)	8,080.60

Sng Ah Tee Motor & Panel Service Pte Ltd/SDH681U/29/12/2022 09:33. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK, WELD, REMOVE & FIX ABOVE PARTS	New	650.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREA	New	450.00
3	TO CHECK WIRING	New	30.00
4	TO DIAGNOSE & RESET FAULT CODE	New	200.00
Gross Labour Cost (S\$)			1,330.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SDH681U/29/12/2022 09:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

L/S or P/P ?
Excess = \$800/-
3 days

9410.6.