

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorised
11/12/22
Recovery After Paint
5 days

ESTIMATE

LIBERTY INSURANCE PTE LTD

51 CLUB STREET

LIBERTY HOUSE #03-11

SINGAPORE 069428

ATTN: ACCIDENT CLAIMS DEPARTMENT

DATE :

27.12.2022

VEHICLE NO :

SKV4734T

VEH MAKE/MODEL :

SUBARU FORESTER

YOM :

2015

CHASSIS NO :

JF1SJGK85FG055671

DATE OF ACCIDENT :

25.12.2022

NO	QTY	DESCRIPTION	AMOUNT \$	
		LIST PRICE:-		
1	1	REAR BUMPER	\$ Bu 540.20	✓
2	2	REAR BUMPER SIDE RETAINER	\$ Bu 32.60	X
3	1	REAR BUMPER TOWING COVER	\$ Bu 16.30	✓
4	1	REAR REINFORCEMENT BAR	\$ 296.40	✓
5	2	REAR BUMPER CENTRE BRACKET	\$ 40.80	✓
6	2	REAR BUMPER REFLECTOR LH & RH	\$ Bu 45.60	X
7	1	REAR END PANEL	\$ 320.90	✓
8	1	REAR END PANEL TOP GARNISH	\$ Bu 89.40	X
9	1	REAR WEATHER SHIELD (TAILGATE RUBBER)	\$ Bu 120.40	✓
10	1	REAR LH LAMP	\$ Bu 437.20	X
11	1	REAR RH LAMP	\$ Bu 437.20	X
12	2	REAR LH & RH LAMP LOWER BRACKET	\$ Bu 40.80	X
13	2	REAR LH & RH LAMP CLIPS	\$ Bu 7.00	X
14	SET	REAR TAILGATE GALSS MOULDING	\$ Bu 89.40	✓
15	1	REAR TAILGATE	\$ Bu 1,072.80	✓
16	1	REAR TAILGATE LOGO	\$ Bu 88.30	✓
17	1	REAR TAILGATE LOGO PANEL	\$ Bu 248.20	✓
18	1	REAR TAILGATE LOGO PANEL RUBBER *LONG	\$ Bu 29.50	X
19	2	REAR TAILGATE LOGO PANEL RUBBER *SHORT	\$ Bu 32.80	X
20	1	REAR TAILGATE " SUBARU AWD"	\$ Bu 72.30	✓
21	1	REAR TAILGATE LOGO " FORESTER XT"	\$ Bu 82.90	✓
22	1	REAR TAILGATE LOCK	\$ Bu 818.40	X
23				
24				
25				
26				
27				
28				
29				
30				
31				
TOTAL - LIST ITEM			\$ 4,959.40	
LIST 20%			\$ 991.88	
TOTAL			\$ 3,967.52	

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

DATE : 27.12.2022
VEHICLE NO : SKV4734T
VEH MAKE/MODEL : SUBARU FORESTER
YOM : 2015
CHASSIS NO : JF1SJGK85FG055671
DATE OF ACCIDENT : 25.12.2022

LIBERTY INSURANCE PTE LTD

51 CLUB STREET

LIBERTY HOUSE #03-11

SINGAPORE 069428

ATTN: ACCIDENT CLAIMS DEPARTMENT

NO	QTY	DESCRIPTION	AMOUNT \$
SPECIAL NETT ITEMS:-			
1	1	REVERSE SENSOR	\$ 360.00
2	SET	REAR BUMPER CLIPS & REAR FENDER SHIELD CLIPS	\$ 60.00
3	2 SET	REAR END PANEL GARNISH CLIPS	\$ 40.00
4	SET	REAR TAILGATE GLASS SEALANT	\$ 80.00
	SET	REAR NUMBER PLATE WITH FRAME	\$ 40.00
5	SET	REAR REVERSE CAMERA	\$ 350.00
Total - SN Item			\$ 930.00
Labour Charges:-			
1		SPRAY PAINT ON ALL AFFECTED AREA	\$ 1,200.00
2		LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	\$ 1,000.00
3		TO CHECK WIRING SYSTEM & LIGHT	\$ 100.00
		TO APPLY ANTI RUST TREATMENT	\$ 120.00
4		TO REMOVE/REFIX REVERSE SENSOR	\$ 150.00
5		TO REMOVE/REFIX REAR INNER COMPARTMENT TO FACILITIES REPAIR	\$ 150.00
6		TO REMOVE/REFIX REAR TAILGATE, TOP SPOILER, WIPER MOTOR, MECHANISM & ETC TO NEW TAILGATE	\$ 300.00
7		TRANSPORT TO APPLICATION TO BREAK VEHICLE NUMBER PLATE FOR FACILITIES	\$ 80.00
8		TRANSPORT FOR RESEAL VEHICLE NUMBER PLATE AFTER REPAIR	\$ 80.00
9		COMPUTER DIAGNOSTIC AFTER REPAIR	\$ 350.00
Total - L/C			\$ 3,530.00
Sub-Total			\$ 8,427.52
7% GST			\$ 589.93
Total			\$ 9,017.45