

ASS. REC. BY:

REF:

AIG/22012871/KP

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

29/12/11 Rpt @ 2250h Car

Veh No:

SHD 528D

Yr Regn:

11, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c

1995

Colour

m. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

37044

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 283512

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

Greenlander 215/60R16

R: Pailun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

15/12/22

D.O.I.

27/12/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

S - RS - SI

Paints

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD528D*Not Notified*
*11/12/2022***AAD2212-071**

Vehicle No.:

Chassis No.:

UEN No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

27 DEC 2022**SHD528D**

VF1ABL15AUC283512

200303878K

RENAULT

LATITUDE

15/12/2022

SLD8292H/AIG

17/11/2017

PART**LIST**

1	BUMPER COVER FRT	\$	<i>Bu</i>	747.20	✓
1	BUMPER BRACKET KIT FRT RH	\$	<i>nn</i>	101.40	X
1	BUMPER RETAINER FRT RH	\$	<i>o.i</i>	101.40	✓
1	FENDER PANEL FRT RH	\$	<i>B</i>	437.10	✓
1	WHEELARCH FRT RH	\$	<i>nn</i>	191.40	X
1	WIPER RESERVOIR	\$	<i>nn</i>	179.60	X
1	HEADLAMP RH	\$	<i>nn</i>	743.60	✓
		\$		2,501.70	
		10% \$		250.17	
		\$		2,251.53	

Specical Nett

1	FRONT BUMPER CLIP	\$	<i>nn</i>	66.00	✓
1	RIM	\$	<i>nn</i>	350.00	X
1	TYRE	\$	<i>nn</i>	300.00	X
1	FENDER LINER CLIP	\$	<i>nn</i>	65.00	X
	TOTAL	\$		781.00	
	TOTAL PARTS	\$		3,032.53	

LABOURTo Remove And Refit Rear Big and Small W/Screen
Glass To Facilitate Bodywork Repair.\$ *nn* 300.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 *4401*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2212-071

SHD528D

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	4001
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To reinstall rear bumper parking sensor.	\$	na 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na 170.00	X
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	na 170.00	X
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201

TOTAL \$ 7,880.00**Over All Total \$ 13,164.06****(LUMP SUM)****Repair Days****02 DAYS****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Company

878K

Vehicle Details

Vehicle No.:

SHD528D

Vehicle to be Exported:

Yes

Intended Deregistration Date:

15 Dec 2022

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE 2.0L DCI AUTO D/AB 4DR

Primary Colour:

Red

Manufacturing Year:

2016

Engine No.:

M9R8839C003192

Chassis No.:

VF1ABL15AUC283512

Maximum Power Output:

127.0 kW (170 bhp)

Open Market Value:

\$19,998.00

Original Registration Date:

17 Nov 2017

First Registration Date:

17 Nov 2017

Transfer Count:

0

Actual ARF Paid:

\$19,998.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

16 Nov 2025

PARF Rebate Amount:

\$13,998.00

Intended COE Rebate Details

COE Expiry Date:

16 Nov 2025

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

8

PQP Paid:

\$33,596.00

COE Rebate Amount:

\$12,260.00

Total Rebate Amount:

\$26,258.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Dec 2022

OK