



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22012983/Avy3e2 Date: 01/03/2023 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5025R	Veh. Inspected	GBC 4719U
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/12/22/2072	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	29/12/2022
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN URVAN	c.c	2953
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	JN1MG4E25Z0797006	Colour	SILVER
	Odometer	301786 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	WINDFORCE	6 mm
	L/H Front Tyre	195 R15C	WINDFORCE	6 mm
	R/H Rear Tyre	195 R15C	WINDFORCE	6 mm
	L/H Rear Tyre	195 R15C	WINDFORCE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/12/2022	Inspection Date	29/12/2022
	Survey held at	YSK AUTO WORKSHOP 1 KAKI BUKIT AVE 6 @ AUTOBAY #01-71 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	