

TAC - No Surveyer

# AUTOTEAM ENGINEERING PTE LTD

7 Gambas Crescent #04-07 Singapore 757087  
Tel: (65) 6253 0233 Email: sales@autoteam.com.sg  
Co. Reg. No. 201205841K

bizSAFE<sub>3</sub>



## QUOTATION

Quote To

**SBS Transit Ltd**  
Seletar Workshop  
3 Yio Chu Kang Crescent  
Singapore 786010

Quotation No. Q22121747  
Date 27 Dec 2022  
Terms Net 30

Attn: Mr Nurizman

| S/No   | Description                                  | ManHour | ManHour Rate | Amount    |
|--|--|---------|--------------|-----------|
| <b><u>Repair Accident Bus - SG 5182M</u></b> |  |         |              |           |
| 1.   | Supply workers for 15 ManHours               | 15      | S\$50.00     | S\$750.00 |
| -  | Replace Signal Light                         |         |              |           |
| -  | Replace Bus-plate Holder                     |         |              |           |
| -  | Replace Right Side Rear Bumper               |         |              |           |
| -  | Repair Left Side Rear Bumper                 |         |              |           |
| -  | Repair Lower Engine Door                     |         |              |           |
| -  | Spray Painting Bus-plate Holder              |         |              |           |
| -  | Spray Painting Left & Right Side Rear Bumper |         |              |           |
| -  | Spray Painting Lower Engine Door             |         |              |           |



Remark(s) All Material To Be Supplied by SBST

**Total S\$750.00**

*This is computer generated. No signature is required.*

**NURIZMAN BIN YUSOFF**  
TECHNICAL OFFICER  
SELETAR BUS WORKSHOP

28 DEC 2022