



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

Ref: CS/SPF22012991/y3

ACCIDENT CLAIMS SECTION

Date: 29/12/2022

(SPORE POLICE FORCE)

POLICE LOGISTICS BASE (PLB)

1 HEMMANT ROAD SINGAPORE 438675

Code: SPF

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 604E	Veh. Inspected	SNC 8056E
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/112	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	29/12/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	27/12/2022	Inspection Date
Survey held at	SUPER-ZEE MOTOR SERVICE BLK 14 DEFU LANE 10 #01-402 SINGAPORE 539195	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
