



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD	Ref: CS3/UOI22013001/Rvy3
146 ROBINSON ROAD	Date: 30/12/2022
#02-01 UOI BUILDINGSINGAPORE 068909	Code: UOI2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBF 274X	Veh. Inspected	SJE 5019U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	KATIE LEE	Assign Date	29/12/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	21/12/2022	Inspection Date	30/12/2022
Survey held at	AF & CARS PTE LTD 48 TOH GUAN ROAD EAST, #01-121, ENTERPRISE HUB, SINGAPORE 608586		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--